

#### **PLEASE NOTE**


- This equipment must be installed and maintained by a qualified electrician in accordance with the appropriate statutory regulations and codes of practice, e.g. Electricity at Work Regulations, BS7671 IET Wiring regulations, etc.
- All applicable local, regional and national regulations must be complied with during the installation, use, maintenance and replacement of this device.
- This device should not be installed if, when unpacking it, you observe that it is damaged.
- Schneider Electric cannot be held responsible in the event of noncompliance with the instructions in this document and in the documents to which it refers.
- The service instruction must be observed throughout the life time of this device.


### **A A** DANGER


#### HAZARD OF ELECTRIC SHOCK, EXPLOSION OR ARC FLASH

- Turn off all power supplying this device before working on it.
- Use a voltage tester with a suitable rated voltage in order to check that all active conductors aren't energized.
- Carefully inspect the work area to check that no tools or objects could have been left inside the equipment.

Failure to follow these instructions will result in death or serious injury.












#### **PLEASE NOTE**


- Remove the minimum number of knockouts required for the incoming and outgoing cables to pass through easily.
- IP rating shall be maintained in accordance with BS7671. Suitable cable protection shall be applied with appropriate conduit.






Printed on 2021/01/13





- can be interchanged.

  2. For incomer position on the right:
- it is recommended to connect neutral cable on the right terminal of the isolator Switch Disconnector for reduced cabling.
- 3.For incomer position on the left: it is recommended to connect neutral cable on the left terminal of the isolator Switch Disconnector for






## DANGER

### HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

- Check that the busbar is fully located in MCB's and incomer.
- Tighten all connections to recommended torque settings.

Failure to follow these instructions will result in death or serious injury.




		ø	Ø	G	0	<b>↔</b>
Incoming switch	20 mm	≤ 50 mm <sup>2</sup>	≤ 35 mm <sup>2</sup>	3.5 N.m	6.5 mm	PZ2
RCCB	16 mm	≤ 35 mm²	≤ 25 mm <sup>2</sup>	3.5 N.m		
MCB 3 - 25 A	16 mm	≤ 25 mm²	≤ 16 mm <sup>2</sup>	2.0 N.m		
MCB 32 - 50 A	16 mm	≤ 35 mm²	≤ 25 mm <sup>2</sup>	3.5 N.m		
RCBO	Lin ≤ 14 mm / L&Nout ≤ 16 mm	Lin ≤ 25 mm²/L&Nout ≤ 16 mm²	Lin ≤ 16 mm <sup>2</sup> /L&Nout ≤ 10 mm <sup>2</sup>	2.0 N.m	5.5 mm	PZ2
Terminal bars	10 mm	≤ 25 mm <sup>2</sup>	≤ 16 mm <sup>2</sup>	2.5 N.m	6.5 mm	PZ2
SPD	16 mm	≤ 35 mm Relea	se <sup>25</sup> fð™Manufacturing	2.5 N.m	6.5 mm	PZ2


Printed on 2021/01/13 NNZ33616-03 3/4

## Finishing Installation


## 7.1 Assembly of Front Cover



# 7.2 Assembly of Pole Filler



## 7.3 Labelling



Schneider Electric Limited Stafford Park 5 Telford TF3 3BL

United Kingdom www.se.com/uk