BadAlloc Vulnerabilities

9 November 2021 (8 April 2025)

Overview

Schneider Electric is aware of multiple memory allocation vulnerabilities dubbed 'BadAlloc', disclosed by Microsoft on April 29, 2021. The impact of a successful exploitation of the vulnerabilities may result in denial of service, or remote code execution, depending on the context.

April 2025 Update: A remediation is available for BMECRA31210, BMXCRA31200, BMXCRA31210 (Page 13) and mitigations for this product have been updated.

Vulnerability Details

The complete list of affected real-time operating systems can be found here: https://uscert.cisa.gov/ics/advisories/icsa-21-119-04.

Affected Products, Remediations & Mitigations

Schneider Electric has determined that the following offers are impacted and has provided remediations, for those listed in the <u>Available Remediations</u> section, and recommended mitigations, for those in the <u>Affected Products</u> section.

Please subscribe to the Schneider Electric security notification service to be informed of critical updates to this notification, including information on affected products and remediation plans:

https://www.se.com/ww/en/work/support/cybersecurity/security-notifications.jsp

Remediations/Final Mitigations

Products & Affected Versions	CVEs	Remediation/Mitigation
Easergy C5x (C52/C53) prior to v1.0.5	CVE-2020- 35198 CVE-2020- 28895	Version 1.0.5 of Easergy C5 includes a fix for these vulnerabilities and is available through Schneider Electric regional DPACs.
Easergy MiCOM P30 range, models: P138, P139, P436, P437, P438, P439, P532, P631, P632, P633, P634, P638, C434 Versions 660 - 674	CVE-2020- 35198 CVE-2020- 28895	Easergy MiCOM P638 Version 676.701 of the P30 firmware includes a fix for these vulnerabilities and is available on request from Schneider Electric's Customer Care All other Easergy MiCOM P30 Models: Version 675 and later of the P30 firmware includes a fix for these vulnerabilities and is available on request from Schneider Electric's Customer Care Center.



Easergy MiCOM P30 range, models: P132, P433, P435 Versions 660 - 674	CVE-2020- 35198, CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Use relays only in a protected environment to minimize network exposure and ensure that they are not accessible from outside. • Disable unused network protocol interfaces. • Use firewalls to protect and separate the control system network from other networks. • Activate and apply user management and password features.
Easergy P5 v01.401.101 and prior	CVE-2020- 28895	Version 01.401.101 of Easergy P5 firmware includes a fix for this vulnerability and is available on request from Schneider Electric's Customer Care Center .
EPC2000 v3.01 firmware version and prior	CVE-2020- 35198 CVE-2020- 28895	Version 4.03 of the EPC2000 includes a fix for these vulnerabilities and is available for download here: https://www.eurotherm.com/?wpdmdl=137741
EPC3000 v5.10 firmware version and prior	CVE-2020- 35198 CVE-2020- 28895	Version 5.20 of the EPC3000 includes a fix for these vulnerabilities and is available for download here: https://www.eurotherm.com/?wpdmdl=89545 Device will reboot automatically after upgrade.
Easy Harmony ET6 (HMIET Series) Vijeo Designer Basic v1.2 family and prior	CVE-2020- 28895 CVE-2020- 35198	Version 1.2.1 of Vijeo Designer Basic includes a fix for these vulnerabilities. Please contact your Schneider Electric's <u>Customer Care Center</u> to obtain the installer. To complete the update, connect to Harmony HMI and download the firmware using Vijeo Designer Basic V1.2.1.
Easy Harmony GXU (HMIGXU Series) Vijeo Designer Basic v1.2 family and prior	CVE-2020- 28895 CVE-2020- 35198	Version 1.2.1 of Vijeo Designer Basic includes a fix for these vulnerabilities. Please contact your Schneider Electric's <u>Customer Care Center</u> to obtain the installer. To complete the update, connect to Harmony HMI and download the firmware using Vijeo Designer Basic V1.2.1.



Eurotherm E+PLC100 All versions	CVE-2020- 35198 CVE-2020- 28895	The E+PLC100 product has reached its end of life and is no longer supported. Customers should immediately apply the following mitigations to reduce the risk of exploit: Setup network segmentation and implement a firewall to block all unauthorized access to the device. Configure the Access Control List following the recommendations of the device user manual. Setup a VPN between the E+PLC100 device and any remote visualization workstations running the E+PLC tools. Activate and apply user management and password features. Limit the access to both development and control system by physical means, operating system features, etc.
Eurotherm E+PLC400 v1.3.0.1 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 1.4.0.0 of the E+PLC400 firmware is available and includes a fix for these vulnerabilities. Please contact the Eurotherm Support team to obtain the firmware update. Please be sure to include the following when contacting the support team: • End Username, Company, and Email Address • Serial numbers of the devices to be upgraded • Current E+PLC400 firmware version
Eurotherm Eycon 10/20 Visual Supervisor v7.2 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 7.3 of the Eycon firmware is available and includes a fix for these vulnerabilities. Access to the patch can be obtained through the following link: https://partners.eurotherm.com/member-login
Eurotherm T2550 PAC v8.1 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 8.2 of the T2550 firmware is available and includes a fix for these vulnerabilities. Access to the patch can be obtained through the following link: https://partners.eurotherm.com/member-login



Eurotherm T2750 PAC v6.2 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 6.3 of the T2750 firmware is available and includes a fix for these vulnerabilities. Access to the patch can be obtained through the following link: https://partners.eurotherm.com/member-login
Harmony/ Magelis HMIGTU Series HMIGTUX Series HMIGK Series Vijeo Designer v6.2 SP11 Hotfix 3 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 6.2 SP11 Multi HotFix 4 of Vijeo Designer includes a fix for these vulnerabilities and can be updated through the Schneider Electric Software Update (SESU) application. On the engineering workstation, update to V6.2 SP11 Multi HotFix 4 (or above) of Vijeo Designer. To complete the update, connect to Harmony HMI and download the project file using Vijeo Designer V6.2 SP11 Multi HotFix 4.
HMISCU Vijeo Designer v6.2 SP11 and prior	CVE-2020- 28895 CVE-2020- 35198	Version 6.2 SP12 of Vijeo Designer includes a fix for these vulnerabilities and can be updated through the Schneider Electric Software Update (SESU) application. On the engineering workstation, update to V6.2 SP12 (or above) of Vijeo Designer. To complete the update, connect to Harmony HMI and download the project file using Vijeo Designer V6.2 SP12.
HMISTU Series Versions prior to V6.3 SP1	CVE-2020- 35198 CVE-2020- 28895	Version 6.3 SP1 of Vijeo Designer includes a fix for these vulnerabilities and can be updated through the Schneider Electric Software Update (SESU) application. https://www.se.com/ww/en/product-range/1054-vijeo-designer-hmisoftware/#software-and-firmware On the engineering workstation, update to V6.3 SP1 (or above) of Vijeo Designer. To complete the update, connect to Harmony HMI and download the project file using Vijeo Designer V6.3 SP1.

JACE-8000 All TAC I/A Series Niagara Framework® platforms prior to Niagara 4.8 are impacted	CVE-2021- 22156	Updates have been released to address the identified vulnerability Customers are urged to upgrade to Niagara 4.10u1. These updates are available on the Schneider Electric Exchange or by contacting your sales support channel or by contacting the Schneider Electric support team at productsupport.NAM-BMS@schneider-electric.com. It is important that all TAC I/A Series Niagara customers for all supported platforms update their systems with these releases to mitigate risk. If you have any questions, please contact your Schneider Electric support team at productsupport.NAM-BMS@schneider-electric.com. As always, we highly recommend that TAC I/A Series Niagara customers running on an unsupported platform (such as Niagara G3/AX) take action to update their systems to a supported platform, ideally the 4.10u1 release of Niagara Framework. In addition to updating your system, Schneider Electric recommends that customers with affected products take the following steps to protect themselves: Review and validate the list of users who are authorized and who can authenticate to Niagara. Allow only trained and trusted persons to have physical access to the system, including devices that have connection to the system though the Ethernet port. Consider using a VPN or other means to ensure secure remote connections into the network where the system is located, If remote connections are enabled. Sign all modules and program objects provided by third-party teams. Review the Niagara Hardening Guide for techniques on securing your
		teams.
MiCOM C264 B5.x up to B5.118 D1.x up to D1.92 D4.x up to D4.38 D5.x up to D5.251 D6.x up to D6.18	CVE-2020- 35198 CVE-2020- 28895	Versions <i>B5.118</i> , <i>D1.92</i> , <i>D4.38</i> , <i>D5.25I</i> and <i>D6.18</i> of MiCOM C264 include a fix for these vulnerabilities and are available through Schneider Electric regional DPACs.



	1	
Modicon M241/M251 Logic Controllers Firmware v5.1.9.34 and prior	CVE- 2020- 28895 CVE- 2020- 35198	Version 5.1.9.34 of Modicon M241/M251 Logic Controllers includes a fix for these vulnerabilities. On the engineering workstation, update to latest version of EcoStruxure Machine Expert: https://www.se.com/ww/en/product-range/2226-ecostruxure-machine-expert-somachine/?parent-subcategory-id=5140&filter=business-1-industrial-automation-and-control To complete the update on Modicon M241/M251 Logic Controllers, update to firmware version V5.1.9.34 or higher available within EcoStruxure Machine Expert. A reboot is needed.
Modicon M262 Logic Controllers Firmware prior to v5.1.6.1	CVE- 2020- 28895 CVE- 2020- 35198	Version 5.1.6.1 of Modicon M262 Logic Controllers includes a fix for these vulnerabilities. On the engineering workstation, update to latest version of EcoStruxure Machine Expert: https://www.se.com/ww/en/product-range/2226-ecostruxure-machine-expert-somachine/?parent-subcategory-id=5140&filter=business-1-industrial-automation-and-control To complete the update on Modicon M262 Logic Controllers, update to firmware version V5.1.6.1 or higher available within EcoStruxure Machine Expert. A reboot is needed.
Modicon M258/ LMC058 Logic Controllers Firmware prior than v5.0.4.18	CVE-2020- 28895 CVE-2020- 35198	Firmware Version 5.0.4.18 of Modicon M258/LMC058 logic controllers includes a fix for these vulnerabilities and can be updated through Schneider Electric Software Update (SESU) application.
Modicon M340 Module BMXNOC0401 prior to v2.11	CVE-2020- 35198 CVE-2020- 28895	Version 2.11 of BMXNOC0401 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product/BMXNOC0401/
Modicon M340 Ethernet Communication Modules BMXNOE0100 (H),	CVE-2020- 35198 CVE-2020- 28895	Version SV3.50 of BMXNOE0100 (H) includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/BMXNOE0100_SV_0 3.50/



Versions prior to SV3.50 BMXNOE0110 (H), Versions prior to SV6.70		Version SV6.70 of BMXNOE0110 (H) includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/BMXNOE0110_SV_0 6.70/
Modicon M340 Module BMXNOR0200 (H) RTU prior to v1.7 IR24	CVE-2020- 35198 CVE-2020- 28895	Version 1.7 IR24 of BMXNOR0200H includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product/BMXNOR0200H/
Modicon M340 CPU (BMXP34*) v3.40 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 3.50 of Modicon M340 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/BMXP34xxxxx SV 03 .50/
Modicon M580 CPU (part numbers BMEP* and BMEH*, excluding M580 CPU Safety) Versions prior to SV4.10	CVE-2020- 35198 CVE-2020- 28895	Version SV4.10 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/BMEx58x0x0 SV04.1 https://www.se.com/ww/en/download/document/BMEx58x0x0 SV04.1
Modicon M580 CPU Safety (part numbers BMEP58*S and BMEH58*S) Versions prior to SV4.21	CVE-2020- 35198 CVE-2020- 28895	Version SV4.21 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product-range/62098-modicon-m580-pac-controller/#software-and-firmware Important: customer needs to use version of EcoStruxure™ Control Expert V16.0 HF001 minimum to connect with the latest version of M580 CPU Safety. The software is available for download here: https://www.se.com/ww/en/product-range/548-ecostruxure-control-expert-unity-pro/#software-and-firmware
Modicon M580 Ethernet Communication Modules (BMENOC0301 & BMENOC0311) Versions prior to SV2.21	CVE-2020- 35198 CVE-2020- 28895	Version SV2.21 includes a fix for these vulnerabilities and is available for download here: BMENOC 0301 - https://www.se.com/ww/en/download/document/BMENOC0301_SV_0_2.21/ BMENOC 0311 - https://www.se.com/ww/en/download/document/BMENOC0311_SV_0_2.21



Modicon M580 NOC Control (BMENOC0321) Versions prior to SV1.09	CVE-2020- 35198 CVE-2020- 28895	Version SV1.09 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/BMENOC0321_SV_0 1.09
HART IO X80 Module (part number BMEAHI0812, BMEAHO0412) Versions prior to SV1.5	CVE-2020- 28895 CVE-2020- 35198	Version SV1.5 of HART X80 Module includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/BMEAHO0412 Firmware upgrade/
Modicon MC80 Controller (BMKC8*) Prior to v1.8	CVE-2020- 35198 CVE-2020- 28895	Version 1.8 of MC80 Controller (BMKC80) includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product-range/62396-modicon-mc80/#software-and-firmware
Modicon Momentum ENT (170ENT11*) All Versions	CVE-2020- 35198 CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Setup network segmentation and implement a firewall to block all unauthorized access to the device. • Configure the Access Control List following the recommendations in the device user manual. • Setup a VPN between the Modicon PLC device and the remote engineering workstations. • Activate and apply user management and password features. • Limit the access to both development and control system by physical means, operating system features, etc.
Modicon Momentum Unity M1E Processor (part numbers 171CBU*) Versions prior to SV2.6	CVE-2020- 35198 CVE-2020- 28895	Version SV2.6 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/download/document/Momentum FW upda te/

Modicon Quantum CPU and Communication Modules All versions	CVE-2020- 28895 CVE-2020- 35198	Quantum and Premium offers have reached their end of life and are no longer supported. Customers should immediately apply the following mitigations to reduce the risk of exploit: • Setup network segmentation and implement a firewall to block all unauthorized access to the device. • Setup a VPN between the Modicon PLC device and the remote engineering workstations. • Activate and apply user management and password features. • Limit the access to both development and control system by physical means, operating system features, etc. Customers should also consider upgrading to the latest product offering Modicon M580 ePAC.
Modicon Premium CPU and Communication Modules All versions	CVE-2020- 28895 CVE-2020- 35198	Quantum and Premium offers have reached their end of life and are no longer supported. Customers should immediately apply the following mitigations to reduce the risk of exploit: • Setup network segmentation and implement a firewall to block all unauthorized access to the device. • Setup a VPN between the Modicon PLC device and the remote engineering workstations. • Activate and apply user management and password features. • Limit the access to both development and control system by physical means, operating system features, etc. Customers should also consider upgrading to the latest product offering Modicon M580 ePAC.
Modicon X80 Module (part number BMXNOM0200) Versions prior to v1.60	CVE-2020- 35198 CVE-2020- 28895	Version 1.60 of BMXNOM0200 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product/BMXNOM0200/



Modicon X80 Module (part number BMENOS0300) Versions prior to v1.04	CVE-2020- 35198 CVE-2020- 28895	Version 1.04 of BMENOS0300 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product/BMENOS0300/
nanodac v9.01 firmware version and prior	CVE-2020- 28895 CVE-2020- 35198	Version 10.02 of nanodac includes a fix for this vulnerability and is available for download here: https://www.eurotherm.com/?wpdmdl=28419 Device will reboot automatically after upgrade.
PacDrive Eco/Pro/Pro2 Logic Controllers Firmware versions prior to v1.66.5.1	CVE-2020- 28895 CVE-2020- 35198	Firmware Version 1.66.5.1 of PacDrive Eco/Pro/Pro2 Logic Controllers includes a fix for these vulnerabilities and can be updated through the Schneider Electric Software Update (SESU) application.
PacDrive M All versions	CVE-2020- 28895 CVE-2020- 35198	PacDrive M Logic Controller has reached its end of life and is no longer supported. Customers should immediately apply the following mitigations to reduce the risk of exploit: • Use controllers and devices only in a protected environment to minimize network exposure and ensure that they are not accessible from outside, • Use firewalls to protect and separate the control system network from other networks, • Use VPN (Virtual Private Networks) tunnels if remote access is required, • Activate and apply user management and password features, • Limit the access to both development and control system by physical means, operating system features, etc. Customers should also consider upgrading to the latest product offering PacDrive Eco/Pro/Pro2 to resolve this issue.



PowerLogic ION7400 Firmware v3.0 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 3.1 of PowerLogic ION7400 includes a fix for this vulnerability and is available for download here: https://www.se.com/ww/en/download/document/ION7400_meter_FW_v003.001.000/ If the update cannot be applied immediately, please follow the guidelines in Schneider Electric Recommended Cybersecurity Best Practices document to help mitigate the risk.
PowerLogic PM8000 Firmware v3.0 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 3.1 of PowerLogic PM8000 includes a fix for this vulnerability and is available for download here: https://www.se.com/ww/en/download/document/PM8000_meter_FW_v_003.001.000/ If the update cannot be applied immediately, please follow the guidelines in Schneider Electric Recommended Cybersecurity Best_Practices document to help mitigate the risk.
PowerLogic ION9000 Firmware v3.0 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 3.1 of PowerLogic ION9000 includes a fix for this vulnerability and is available for download here: https://www.se.com/ww/en/download/document/ION9000 meter FW v003.001.000/ If the update cannot be applied immediately, please follow the guidelines in Schneider Electric Recommended Cybersecurity Best Practices document to help mitigate the risk.
Pro-face SP-5B00, SP-5B10, SP-5B90, ST6000 Series (GP-ProEX model), ET6000 Series GP-Pro EX v4.09.300 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 4.09.350 of Pro-face GP-Pro EX includes a fix for these vulnerabilities and is available for download here: https://www.proface.com/en/download/trial/gpproex/v40 or update online via GP-Pro EX (refer to Help menu and select "Confirm Update of GP-Pro EX"). To complete the update, connect to Pro-face HMI and download the project file using GP-Pro EX V4.09.350 or later.
Pro-face LT4000M Series GP-Pro EX v4.09.450 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 4.09.450 of Pro-face GP-Pro EX includes a fix for these vulnerabilities and is available for download here: https://www.proface.com/en/download/trial/gpproex/v40 or update online via GP-Pro EX (refer to Help menu and select "Confirm Update of GP-Pro EX").



		To complete the update, connect to Pro-face HMI and download the project file using GP-Pro EX V4.09.400 or later.
Pro-face GP4000 Series, GP4000H Series GP-Pro EX v4.09.350 and prior	CVE-2020- 35198 CVE-2020- 28895	Version 4.09.400 of Pro-face GP-Pro EX includes a fix for these vulnerabilities and is available for download here: https://www.proface.com/en/download/trial/gpproex/v40 or update online via GP-Pro EX (refer to Help menu and select "Confirm Update of GP-Pro EX"). To complete the update, connect to Pro-face HMI and download the project file using GP-Pro EX V4.09.400 or later.
Profibus Remote Master TCSEGPA23F14F, BMECXM0100 All versions	CVE-2020- 35198 CVE-2020- 28895	Customers should immediately apply the mitigations found in the Cybersecurity Reference Manual linked below to reduce the risk of exploit: https://www.se.com/ww/en/download/document/EIO0000001999/
SCD6000 Industrial RTU Version SCD6000 SY1101211_M and prior	CVE-2020- 35198 CVE-2020- 28895	Version SY-1101207, Version N of SCD6000 firmware includes a fix for this vulnerability. Contact your local Customer Support to receive this firmware version. Reboot is required after installation.
SAGE RTU CPU C3414 All versions prior to C3414-500- S02K5_P5	CVE-2020- 35198 CVE-2020- 28895	Version C3414-500-S02K5_P5 of SAGE RTU CPU 3414 includes a fix for this vulnerability and is available for download here: https://www.sage-rtu.com/downloads.html Reboot of SAGE RTU is required after firmware upgrade. This fix applies a Wind River VxWorks (real-time operating system) patch to bring code libraries current to 6.9.4.12 RCPL3 revision. This corrects issues with overflow causing malloc/calloc to return valid pointer when it should return fail indication NULL pointer.



Versadac Versions prior to v2.41 firmware	CVE-2020- 35198 CVE-2020- 28895	Version 2.43 of the Versadac scalable data recorder is available and includes a fix for these vulnerabilities. Access to the patch can be obtained through the following link: https://partners.eurotherm.com/member-login
BMECRA31210, BMXCRA31200, BMXCRA31210, Versions prior to SV02.80 firmware	CVE-2020- 35198 CVE-2020- 28895	Version SV02.80 of BMECRA31210, BMXCRA3120, BMXCRA31210 includes a fix for these vulnerabilities and is available for download here: https://www.se.com/ww/en/product-country-selector/?pageType=product&sourceId=BMXCRA31210

Affected Products

Schneider Electric is currently establishing a remediation plan for the following products. This document will be updated when product specific information is available. Until then, customers should immediately apply the following mitigations to reduce the risk of exploit.

Please subscribe to the Schneider Electric security notification service to be informed of critical updates to this notification, including information on affected products and remediation plans: https://www.se.com/ww/en/work/support/cybersecurity/security-notifications.jsp

For additional information and support, please contact your Schneider Electric sales or service representative or <u>Schneider Electric's Customer Care Center</u>.

Recommended Mitigations

Products	CVEs	Recommended Mitigation
140CRA31200, 140CRA31908 All Versions	CVE-2020- 35198 CVE-2020-	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Setup network segmentation and implement a firewall to block all unauthorized access to the device. • Configure the Access Control List following the recommendations of the device user manual.
BMXNGD0100, All Versions	 Setup a VPN between the Modicon. Communication modules and the remote engineering workstations. Activate and apply user management and password features. 	



BMENOP0300 All Versions		 Limit the access to both development and control system by physical means, operating system features, etc.
Easergy MiCOM P30 range, model Px36/8 Versions 660 - 674	CVE-2020- 35198, CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Use relays only in a protected environment to minimize network exposure and ensure that they are not accessible from outside. • Disable unused network protocol interfaces.
Easergy MiCOM P40 All versions	CVE-2020- 28895	 Use firewalls to protect and separate the control system network from other networks. Activate and apply user management and password features. Limit the access to the system by physical means.
EPack All versions	CVE-2020- 35198 CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit:
HMISTO5 Series All versions	CVE-2020- 35198 CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Locate control and safety system networks and remote devices behind firewalls and isolate them from the business network. • Install physical controls so no unauthorized personnel can access your industrial control and safety systems, components, peripheral equipment, and networks. • Minimize network exposure for all control system devices and systems and ensure that they are not accessible from the Internet. When remote access is required, use secure methods, such as the Vijeo Connect.

Modicon LMC078 All versions	CVE-2020- 28895 CVE-2020- 35198	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Use controllers and devices only in a protected environment to minimize network exposure and ensure that they are not accessible from outside, • Use firewalls to protect and separate the control system network from other networks, • Use VPN (Virtual Private Networks) tunnels if remote access is required, • Activate and apply user management and password features, • Limit the access to both development and control system by physical means, operating system features, etc. Customers should also consider upgrading to the latest product offering Modicon M262 to resolve this issue.
Pro-face GP4100 Series, GP4000E Series, GP4000M Series All versions	CVE-2020- 35198, CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit: • Locate control and safety system networks and remote devices behind firewalls and isolate them from the business network. • Install physical controls so no unauthorized personnel can access your industrial control and safety systems, components, peripheral equipment, and networks. • Minimize network exposure for all control system devices and systems and ensure that they are not accessible from the Internet. • When remote access is required, use secure methods, such as the Pro-face Connect. Customers should also consider upgrading to the latest product offering to resolve this issue. Please contact your sales support about alternative products



6100A, 6180A, 6100XIO, 6180XIO, AeroDAQ	CVE-2020- 35198 CVE-2020- 28895	Customers should immediately apply the following mitigations to reduce the risk of exploit: Setup network segmentation and implement a firewall to block all unauthorized access to the device. Configure the Access Control List following the recommendations of the device user manual. Setup a VPN between the 6000-series device and any remote visualization workstations running Bridge
AeroDAQ All versions		remote visualization workstations running Bridge. • Activate and apply user management and password features. Limit the access to both development and control system by physical means, operating system features, etc.

General Security Recommendations

We strongly recommend the following industry cybersecurity best practices.

- Locate control and safety system networks and remote devices behind firewalls and isolate them from the business network.
- Install physical controls so no unauthorized personnel can access your industrial control and safety systems, components, peripheral equipment, and networks.
- Place all controllers in locked cabinets and never leave them in the "Program" mode.
- Never connect programming software to any network other than the network intended for that device.
- Scan all methods of mobile data exchange with the isolated network such as CDs, USB drives, etc. before use in the terminals or any node connected to these networks.
- Never allow mobile devices that have connected to any other network besides the intended network to connect to the safety or control networks without proper sanitation.
- Minimize network exposure for all control system devices and systems and ensure that they are not accessible from the Internet.
- When remote access is required, use secure methods, such as Virtual Private Networks (VPNs).
 Recognize that VPNs may have vulnerabilities and should be updated to the most current version available. Also, understand that VPNs are only as secure as the connected devices.

For more information refer to the Schneider Electric Recommended Cybersecurity Best Practices document.

For More Information

This document provides an overview of the identified vulnerability or vulnerabilities and actions required to mitigate. For more details and assistance on how to protect your installation, contact your local Schneider Electric representative or Schneider Electric Industrial Cybersecurity Services:

<u>https://www.se.com/ww/en/work/solutions/cybersecurity/</u>. These organizations will be fully aware of this situation and can support you through the process.



For further information related to cybersecurity in Schneider Electric's products, visit the company's cybersecurity support portal page: https://www.se.com/ww/en/work/support/cybersecurity/overview.jsp

LEGAL DISCLAIMER

THIS NOTIFICATION DOCUMENT, THE INFORMATION CONTAINED HEREIN, AND ANY MATERIALS LINKED FROM IT (COLLECTIVELY, THIS "NOTIFICATION") ARE INTENDED TO HELP PROVIDE AN OVERVIEW OF THE IDENTIFIED SITUATION AND SUGGESTED MITIGATION ACTIONS, REMEDIATION, FIX, AND/OR GENERAL SECURITY RECOMMENDATIONS AND IS PROVIDED ON AN "AS-IS" BASIS WITHOUT WARRANTY OR GUARANTEE OF ANY KIND. SCHNEIDER ELECTRIC DISCLAIMS ALL WARRANTIES RELATING TO THIS NOTIFICATION, EITHER EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SCHNEIDER ELECTRIC MAKES NO WARRANTY THAT THE NOTIFICATION WILL RESOLVE THE IDENTIFIED SITUATION. IN NO EVENT SHALL SCHNEIDER ELECTRIC BE LIABLE FOR ANY DAMAGES OR LOSSES WHATSOEVER IN CONNECTION WITH THIS NOTIFICATION, INCLUDING DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, LOSS OF BUSINESS PROFITS OR SPECIAL DAMAGES, EVEN IF SCHNEIDER ELECTRIC HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. YOUR USE OF THIS NOTIFICATION IS AT YOUR OWN RISK, AND YOU ARE SOLELY LIABLE FOR ANY DAMAGES TO YOUR SYSTEMS OR ASSETS OR OTHER LOSSES THAT MAY RESULT FROM YOUR USE OF THIS NOTIFICATION. SCHNEIDER ELECTRIC RESERVES THE RIGHT TO UPDATE OR CHANGE THIS NOTIFICATION AT ANY TIME AND IN ITS SOLE DISCRETION

About Schneider Electric

Schneider's purpose is to **create Impact** by empowering all **to make the most of our energy and resources**, bridging progress and sustainability for all. We call this Life Is On.

Our mission is to be the trusted partner in **Sustainability and Efficiency**.

We are a **global industrial technology leader** bringing world-leading expertise in electrification, automation and digitization to smart **industries**, resilient **infrastructure**, future-proof **data centers**, intelligent **buildings**, and intuitive **homes**. Anchored by our deep domain expertise, we provide integrated end-to-end lifecycle Al enabled Industrial IoT solutions with connected products, automation, software and services, delivering digital twins to enable profitable growth **for our customers**.

We are a **people company** with an ecosystem of 150,000 colleagues and more than a million partners operating in over 100 countries to ensure proximity to our customers and stakeholders. We embrace **diversity and inclusion** in everything we do, guided by our meaningful purpose of a **sustainable future for all**.

www.se.com

Revision Control:

Version 1.0.0 09 November 2021	Original Release
Version 1.1.0 17 November 2021	Fixed version number of PacDrive Eco/Pro/Pro2 Logic Controllers corrected to v1.66.5.1.



Version 2.0.0 14 December 2021	Remediations added for SCD6000 Industrial RTU, PowerLogic ION7400, PowerLogic ION8000, PowerLogic ION9000. Upon further investigation Tricon Communication Modules have been removed from list of affected products and are not impacted by the Badalloc Vulnerabilities.
Version 3.0.0 15 December 2021	Remediations added for PowerLogic ION9000.
Version 4.0.0 11 January 2022	Remediations added for Easergy P5, EPC3000, Harmony/ Magelis HMIGTU Series, HMIGTUX Series, HMIGK Series, nanodac, Pro-face SP-5B00, SP-5B10,SP-5B90,ST6000 Series (GP-ProEX model), ET6000 Series in the <u>Available Remediations</u> section (page 1, 2, 4, and 6). Updated versions affected to all versions for Pro-face GP4000 Series, LT4000M Series, GP4000H Series in the <u>Affected Versions</u> section.
Version 4.1.0 <i>13 January 2022</i>	Moved back to affected products section: Harmony/ Magelis HMIGTU Series, HMIGTUX Series, HMIGK Series.
Version 5.0.0 08 February 2022	Available remediations for Easy Harmony ET6 (HMIET Series), Easy Harmony GXU (HMIGXU Series), Harmony/ Magelis (HMIGTU Series, HMIGTUX Series, HMIGK Series), Modicon M262 Logic Controllers, and Modicon M241/M251 Logic Controllers. Added Easergy MiCOM P30 and Easergy MiCOM P40 to the list of affected products.
Version 6.0.0 12 April 2022	Added remediations for Eurotherm E+PLC400, Eurotherm T2750 PAC and Modicon M340 CPU. Additionally, Eurotherm T2550 PAC and Eurotherm Eycon 10/20 Visual Supervisor have been added as affected products to this security notification in the remediation section.
Version 7.0.0 10 May 2022	Added a remediation for HMISCU, added the following affected models to the Easergy MiCOM P30 range: C434, P132, P139, P433, P435, P437, P532, P631, P632, P633, P634, Px36/8.
Version 8.0.0 14 June 2022	Added a remediation for EPC2000, v4.03 includes a fix.
Version 9.0.0 <i>15 June 2022</i>	Remediation added for Versadac. The previously added remediation for EPC2000 has been removed as v4.03 is not yet available, this document will be updated when it is released.
Version 10.0.0 09 August 2022	Remediations available for Modicon M580 CPU (BMEP* and BMEH*) and Pro-face GP4000 Series, GP4000H Series GP-Pro EX.



Version 11.0.0 13 September 2022	Final Remediations available for Modicon M340 Modules BMXNOC0401 and BMXNOR0200H RTU, and Modicon MC80 Controller (BMKC8*). There is a mitigation available for Profibus Remote Master (TCSEGPA23F14F) and CANopen X80 Communication Module (BMECXM0100).
Version 12.0.0 11 October 2022	Easergy MiCOM P30 range P632 and P633 were added as affected models along with a remediation. Final mitigations were added for Modicon Momentum ENT. Adding a clarification to the list of affected products by splitting Modicon M580 and Modicon M580 Safety CPU ranges; the latest fix Modicon M580 v4.02 does not apply to the Safety range of M580.
Version 13.0.0 08 November 2022	A remediation is now available for EPC2000.
Version 14.0.0 13 December 2022	The Modicon M580 SV4.02 firmware has been retracted for quality issues and is no longer available for download. Additional mitigations have been introduced for Modicon M580 CPU and M580 CPU Safety, and we urge customers to deploy these mitigations to further reduce the risk of potential exploitation of identified vulnerabilities.
Version 15.0.0 <i>10 January 2023</i>	There are remediations available for Easergy MiCOM P30 range and Pro-face LT4000M Series.
Version 16.0.0 <i>14 February 2023</i>	There is a remediation for Modicon M340 Ethernet Communication Modules BMXNOE0100 (H) and BMXNOE0110 (H) products.
Version 17.0.0 <i>14 March 2023</i>	Remediations for the following products are now available: Easergy MiCOM P30 range models P139, P437, P439, P532, P631, P632, P633, P634, C434 (page 2), Modicon M580 CPU part numbers BMEP* and BMEH (page 7), and Modicon Momentum Unity M1E Processor part numbers 171CBU* (page 8). Mitigations for Easergy MiCOM P30 range, models P138, P436, P438, P132, P433, P435 have been added.
Version 18.0.0 <i>11 April 2023</i>	Remediations are now available for Modicon M580 Ethernet Communication Modules BMENOC*.
Version 19.0.0 09 May 2023	A remediation is now available for Modicon X80 Module (part number BMXNOM0200).
Version 20.0.0 11 July 2023	A remediation is now available for HART IO X80 Module (part number BMEAHI0812, BMEAHO0412).



Version 21.0.0 12 March 2024	Easergy MiCOM P30 range models 139 and 436 were added to Affected Products.
Version 22.0.0 13 August 2024	A remediation is available on Modicon M580 CPU Safety.
Version 23.0.0 10 September 2024	A remediation is available on HMISTU (page 4).
Version 24.0.0 12 November 2024	Changes have been made to the Easergy MiCOM P30 remediation description and we have added model P638 to the list of Easergy MiCOM P30s with a remediation.
Version 25.0.0 14 January 2025	A remediation is available for Modicon X80 module, part number BMENOS0300 (Page 10).
Version 26.0.0 08 April 2025	A remediation is available for BMECRA31210, BMXCRA31200, BMXCRA31210 (Page 13) and mitigations for this product have been updated.