

# Schneider Electric Security Notification

## Modicon PAC Controllers

9 August 2022 (13 August 2024)

### Overview

Schneider Electric is aware of a vulnerability in its Modicon PAC Controllers.

[Modicon PLCs \(Programmable Logic Controllers\) and PACs \(Programmable Automation Controllers\)](#) control and monitor industrial operations in a sustainable, flexible, efficient and protected way.

Failure to apply the remediations provided below may risk read access to memory content of the controllers, which could result in exposure of sensitive information such as application password hash and project data to the attacker.

**August 2024 Update:** A remediation is available for the Modicon M580 CPU Safety ([page 2](#)).

### Affected Products and Versions

Product	Version
Modicon M340 CPU (part numbers BMXP34*)	Versions prior to v3.40
Modicon M580 CPU (part numbers BMEP* and BMEH*, excluding M580 CPU Safety)	Versions prior to v4.20
Modicon M580 CPU Safety (part numbers BMEP58*S and BMEH58*S)	Versions prior to SV4.21
Modicon MC80 (BMKC80)	Versions prior to v1.70
Modicon Momentum CPU (171CBU*)	Versions prior to v2.4
Legacy Modicon Quantum	All versions

### Vulnerability Details

CVE ID: **CVE-2021-22786**

CVSS v3.1 Base Score 7.5 | High | CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N

*CWE-200: Information Exposure* vulnerability exists that could cause the exposure of sensitive information stored on the memory of the controller when communicating over the Modbus TCP protocol.

## Schneider Electric Security Notification

### Remediation

Affected Products	Remediations
<b>Modicon Modicon M340 CPU (part numbers BMXP34*)</b> <i>Versions prior to v3.40</i>	Firmware v3.40 of Modicon includes a fix for this vulnerability and is available for download here: <a href="https://www.se.com/ww/en/download/document/BMXP34xxxxx_SVxx.xx/">https://www.se.com/ww/en/download/document/BMXP34xxxxx_SVxx.xx/</a>
<b>Modicon M580 CPU (part numbers BMEP* and BMEH*, excluding M580 CPU Safety)</b> <i>Versions prior to v4.10</i>	Firmware v4.10 includes a fix for this vulnerability and is available for download here: <a href="https://www.se.com/ww/en/download/document/BMEx58x0x0_SV04.10/">https://www.se.com/ww/en/download/document/BMEx58x0x0_SV04.10/</a>
<b>Modicon M580 CPU Safety (part numbers BMEP58*S and BMEH58*S)</b> <i>Versions prior to SV4.21</i>	Firmware SV4.21 includes a fix this vulnerability and is available for download here: <a href="https://www.se.com/ww/en/product-range/62098-modicon-m580-pac-controller/#software-and-firmware">https://www.se.com/ww/en/product-range/62098-modicon-m580-pac-controller/#software-and-firmware</a>  Important: customer needs to use version of EcoStruxure™ Control Expert V16.0 HF001 minimum to connect with the latest version of M580 CPU Safety. The software is available for download here: <a href="https://www.se.com/ww/en/product-range/548-ecostruxure-control-expert-unity-pro/#software-and-firmware">https://www.se.com/ww/en/product-range/548-ecostruxure-control-expert-unity-pro/#software-and-firmware</a>
<b>Modicon MC80 (BMKC80)</b> <i>Versions prior to v1.70</i>	Firmware V1.70 includes a fix for this vulnerability and is available for download here: <a href="https://www.se.com/ww/en/download/document/BMKC80_Firmware_upgrade/">https://www.se.com/ww/en/download/document/BMKC80_Firmware_upgrade/</a>
<b>Modicon MOMENTUM CPU (171CBU*)</b> <i>Versions prior to v2.4</i>	Firmware V2.4 includes a fix for this vulnerability and is available for download here: <a href="https://www.se.com/ww/en/download/document/Momentum_FW_update/">https://www.se.com/ww/en/download/document/Momentum_FW_update/</a>

## Schneider Electric Security Notification

<b>Legacy Modicon Quantum</b> <i>All versions</i>	<p>Schneider Electric's Modicon Quantum controllers have reached their end of life and are no longer commercially available. They have been replaced by the Modicon M580 ePAC Controller, our current product offer.</p> <p>Customers should strongly consider migrating to the Modicon M580 ePAC.</p> <p>Please contact your local Schneider Electric technical support for more information.</p>
--	--

Customers should use appropriate patching methodologies when applying these patches to their systems. We strongly recommend the use of back-ups and evaluating the impact of these patches in a Test and Development environment or on an offline infrastructure. Contact Schneider Electric's [Customer Care Center](#) if you need assistance removing a patch.

If customers choose not to apply the remediation provided above, they should immediately apply the mitigations provided in the table below.

Affected Product	Mitigations
<b>Modicon M340 CPU (part numbers BMXP34*)</b> <i>Versions prior to v3.40</i>	<ul style="list-style-type: none"> <li>• Setup an application password in the project properties.</li> <li>• Setup network segmentation and implement a firewall to block all unauthorized access to port 502/TCP.</li> <li>• Configure the Access Control List following the recommendations of the user manuals: <ul style="list-style-type: none"> <li>○ "Modicon M340 for Ethernet Communications Modules and Processors User Manual" in chapter "Messaging Configuration Parameters":  <a href="https://www.se.com/ww/en/download/document/31007131K01000/">https://www.se.com/ww/en/download/document/31007131K01000/</a></li> <li>○ "Modicon MC80 Programmable Logic Controller (PLC) manual" in the chapter "Access Control List (ACL)"  <a href="https://download.schneider-electric.com/files?p_enDocType=User+guide&amp;p_File_Name=EIO0000002071.02.pdf&amp;p_Doc_Ref=EIO0000002071">https://download.schneider-electric.com/files?p_enDocType=User+guide&amp;p_File_Name=EIO0000002071.02.pdf&amp;p_Doc_Ref=EIO0000002071</a></li> <li>○ "Momentum for EcoStruxure™ Control Expert – 171 CBU 78090, 171 CBU 98090, 171 CBU 98091 Processors" manual in the chapter "Modbus Messaging and Access Control" <a href="https://download.schneider-electric.com/files?p_enDocType=User+guide&amp;p_File_Name=HRB44124.08.pdf&amp;p_Doc_Ref=HRB44124">https://download.schneider-electric.com/files?p_enDocType=User+guide&amp;p_File_Name=HRB44124.08.pdf&amp;p_Doc_Ref=HRB44124</a></li> </ul> </li> <li>• Setup a secure communication according to the following guideline "Modicon Controllers Platform Cyber Security Reference Manual," in chapter "Setup secured communications":  <a href="https://www.se.com/ww/en/download/document/EIO0000001999/">https://www.se.com/ww/en/download/document/EIO0000001999/</a></li> </ul>
<b>Modicon MC80 (BMKC80)</b> <i>Versions prior to v1.70</i>	

## Schneider Electric Security Notification

<p><b>Modicon MOMENTUM CPU (171CBU*)</b> <i>Versions prior to v2.4</i></p>	<ul style="list-style-type: none"> <li>• Use a BMENOC module and follow the instructions to configure IPSEC feature as described in the guideline “Modicon M580 – BMENOC03.1 Ethernet Communications Schneider Electric Security Notification Module, Installation and Configuration Guide” in the chapter “Configuring IPSEC communications”: <a href="https://www.se.com/ww/en/download/document/HRB62665/">https://www.se.com/ww/en/download/document/HRB62665/</a></li> <li>• Setup a VPN between the Modicon PLC controller and the engineering workstation containing EcoStruxure Control Expert or Process Expert. Note: this functionality may be provided by an external IPSEC compatible firewall located close to the controller.</li> </ul> <p>To ensure you are informed of all updates, including details on affected products and remediation plans, subscribe to Schneider Electric’s security notification service here: <a href="https://www.se.com/en/work/support/cybersecurity/security-notifications.jsp">https://www.se.com/en/work/support/cybersecurity/security-notifications.jsp</a></p>
<p><b>Modicon M580 CPU</b> <i>Versions prior to v4.20</i></p>	<ul style="list-style-type: none"> <li>• Setup network segmentation and implement a firewall to block all unauthorized access to port 502/TCP.</li> <li>• Configure the Access Control List following the recommendations of the user manual “Modicon M580, Hardware, Reference Manual”: <a href="https://www.se.com/ww/en/download/document/EIO0000001578/">https://www.se.com/ww/en/download/document/EIO0000001578/</a></li> <li>• Setup a secure communication according to the following guideline “Modicon Controllers Platform Cyber Security Reference Manual,” in chapter “Setup secured communications”: <a href="https://www.se.com/ww/en/download/document/EIO0000001999/">https://www.se.com/ww/en/download/document/EIO0000001999/</a> Use a BMENUA0100 module and follow the instructions to configure IPSEC feature as described in the chapter “Configuring the BMENUA0100 Cybersecurity Settings”: <a href="https://www.se.com/ww/en/download/document/PHA83350">https://www.se.com/ww/en/download/document/PHA83350</a></li> <li>• Use a BMENOC module and follow the instructions to configure IPSEC feature as described in the guideline “Modicon M580 – BMENOC03.1 Ethernet Communications Schneider Electric Security Notification Module, Installation and Configuration Guide” in the chapter “Configuring IPSEC communications”: <a href="https://www.se.com/ww/en/download/document/HRB62665/">https://www.se.com/ww/en/download/document/HRB62665/</a></li> <li>• Setup a VPN between the Modicon PLC impacted modules and the engineering workstation containing EcoStruxure™ Control Expert or Process Expert.</li> <li>• Ensure the M580 CPU is running with the memory protection activated by configuring the input bit to a physical input, for more details refer to the following guideline “Modicon Controllers Platform Cyber Security Reference Manual”, “CPU Memory Protection section”: <a href="https://www.schneider-electric.com/en/download/document/EIO0000001999/">https://www.schneider-electric.com/en/download/document/EIO0000001999/</a></li> </ul>

## Schneider Electric Security Notification

	<ul style="list-style-type: none"> <li>NOTE: The CPU memory protection cannot be configured with Hot Standby CPUs. In such cases, use IPsec encrypted communication</li> </ul>
<b>Modicon M580 Safety CPU</b> <b>(part numbers BMEP58*S and BMEH58*S)</b> <i>Versions prior to v4.21</i>	<ul style="list-style-type: none"> <li>Setup network segmentation and implement a firewall to block all unauthorized access to port 502/TCP.</li> <li>Configure the Access Control List following the recommendations of the user manual “Modicon M580, Hardware, Reference Manual”:  <a href="https://www.se.com/ww/en/download/document/EIO0000001578/">https://www.se.com/ww/en/download/document/EIO0000001578/</a></li> <li>Setup a secure communication according to the following guideline “Modicon Controllers Platform Cyber Security Reference Manual,” in chapter “Setup secured communications”:  <a href="https://www.se.com/ww/en/download/document/EIO0000001999/">https://www.se.com/ww/en/download/document/EIO0000001999/</a></li> <li>Use a BMENUA0100 module and follow the instructions to configure IPSEC feature as described in the chapter “Configuring the BMENUA0100 Cybersecurity Settings”:  <a href="https://www.se.com/ww/en/download/document/PHA83350">https://www.se.com/ww/en/download/document/PHA83350</a></li> <li>Use a BMENOC module and follow the instructions to configure IPSEC feature as described in the guideline “Modicon M580 – BMENOC03.1 Ethernet Communications Schneider Electric Security Notification Module, Installation and Configuration Guide” in the chapter “Configuring IPSEC communications”:  <a href="https://www.se.com/ww/en/download/document/HRB62665/">https://www.se.com/ww/en/download/document/HRB62665/</a></li> <li>Setup a VPN between the Modicon PLC impacted modules and the engineering workstation containing EcoStruxure™ Control Expert or Process Expert.</li> <li>Ensure the CPU is running with the memory protection activated by configuring the input bit to a physical input , for more details refer to the following guideline “Modicon Controllers Platform Cyber Security Reference Manual”, “CPU Memory Protection section”: <a href="https://www.schneider-electric.com/en/download/document/EIO0000001999/">https://www.schneider-electric.com/en/download/document/EIO0000001999/</a> <ul style="list-style-type: none"> <li>NOTE: The CPU memory protection cannot be configured with Hot Standby CPUs. In such cases, use IPsec encrypted communication</li> </ul> </li> </ul> <p>To further reduce the attack surface on Modicon M580 CPU Safety:</p> <ul style="list-style-type: none"> <li>Ensure the CPU is running in Safety mode and maintenance input is configured to maintain this Safety mode during operation – refer to the document Modicon M580 - Safety System Planning Guide - in the chapter “Operating Mode Transitions”:  <a href="https://www.se.com/ww/en/download/document/QGH60283/">https://www.se.com/ww/en/download/document/QGH60283/</a></li> </ul>

## Schneider Electric Security Notification

<b>Legacy Modicon Quantum</b> All versions	<ul style="list-style-type: none"> <li>• Setup network segmentation and implement a firewall to block all unauthorized access to port 502/TCP.</li> <li>• Configure the Access Control List feature as mentioned in “Quantum using EcoStruxure™ Control Expert – TCP/IP Configuration, User Manual” in chapter “Software Settings for Ethernet Communication / Messaging / Quantum NOE Ethernet Messaging Configuration”: <a href="https://www.se.com/ww/en/download/document/33002467K01000/">https://www.se.com/ww/en/download/document/33002467K01000/</a></li> </ul>
---	--

## General Security Recommendations

We strongly recommend the following industry cybersecurity best practices.

- Locate control and safety system networks and remote devices behind firewalls and isolate them from the business network.
- Install physical controls so no unauthorized personnel can access your industrial control and safety systems, components, peripheral equipment, and networks.
- Place all controllers in locked cabinets and never leave them in the “Program” mode.
- Never connect programming software to any network other than the network intended for that device.
- Scan all methods of mobile data exchange with the isolated network such as CDs, USB drives, etc. before use in the terminals or any node connected to these networks.
- Never allow mobile devices that have connected to any other network besides the intended network to connect to the safety or control networks without proper sanitation.
- Minimize network exposure for all control system devices and systems and ensure that they are not accessible from the Internet.
- When remote access is required, use secure methods, such as Virtual Private Networks (VPNs). Recognize that VPNs may have vulnerabilities and should be updated to the most current version available. Also, understand that VPNs are only as secure as the connected devices.

For more information refer to the Schneider Electric [Recommended Cybersecurity Best Practices](#) document.

## Acknowledgements

Schneider Electric recognizes the following researcher for identifying and helping to coordinate a response to this vulnerability:

CVE	Researcher
CVE-2021-22786	Jie Chen, NSFfocus

# Schneider Electric Security Notification

## For More Information

This document provides an overview of the identified vulnerability or vulnerabilities and actions required to mitigate. For more details and assistance on how to protect your installation, contact your local Schneider Electric representative or Schneider Electric Industrial Cybersecurity Services: <https://www.se.com/ww/en/work/solutions/cybersecurity/>. These organizations will be fully aware of this situation and can support you through the process.

For further information related to cybersecurity in Schneider Electric's products, visit the company's cybersecurity support portal page:

<https://www.se.com/ww/en/work/support/cybersecurity/overview.jsp>

## LEGAL DISCLAIMER

THIS NOTIFICATION DOCUMENT, THE INFORMATION CONTAINED HEREIN, AND ANY MATERIALS LINKED FROM IT (COLLECTIVELY, THIS "NOTIFICATION") ARE INTENDED TO HELP PROVIDE AN OVERVIEW OF THE IDENTIFIED SITUATION AND SUGGESTED MITIGATION ACTIONS, REMEDIATION, FIX, AND/OR GENERAL SECURITY RECOMMENDATIONS AND IS PROVIDED ON AN "AS-IS" BASIS WITHOUT WARRANTY OR GUARANTEE OF ANY KIND. SCHNEIDER ELECTRIC DISCLAIMS ALL WARRANTIES RELATING TO THIS NOTIFICATION, EITHER EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SCHNEIDER ELECTRIC MAKES NO WARRANTY THAT THE NOTIFICATION WILL RESOLVE THE IDENTIFIED SITUATION. IN NO EVENT SHALL SCHNEIDER ELECTRIC BE LIABLE FOR ANY DAMAGES OR LOSSES WHATSOEVER IN CONNECTION WITH THIS NOTIFICATION, INCLUDING DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, LOSS OF BUSINESS PROFITS OR SPECIAL DAMAGES, EVEN IF SCHNEIDER ELECTRIC HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. YOUR USE OF THIS NOTIFICATION IS AT YOUR OWN RISK, AND YOU ARE SOLELY LIABLE FOR ANY DAMAGES TO YOUR SYSTEMS OR ASSETS OR OTHER LOSSES THAT MAY RESULT FROM YOUR USE OF THIS NOTIFICATION. SCHNEIDER ELECTRIC RESERVES THE RIGHT TO UPDATE OR CHANGE THIS NOTIFICATION AT ANY TIME AND IN ITS SOLE DISCRETION

## About Schneider Electric

Schneider's purpose is to empower all to make the most of our energy and resources, bridging progress and sustainability for all. We call this Life Is On.

Our mission is to be your digital partner for Sustainability and Efficiency.

We drive digital transformation by integrating world-leading process and energy technologies, end-point to cloud connecting products, controls, software and services, across the entire lifecycle, enabling integrated company management, for homes, buildings, data centers, infrastructure and industries.

We are the most local of global companies. We are advocates of open standards and partnership ecosystems that are passionate about our shared Meaningful Purpose, Inclusive and Empowered values.

[www.se.com](https://www.se.com)



## Schneider Electric Security Notification

Revision Control:

<b>Version 1.0.0</b> <i>09 August 2022</i>	<b>Original Release</b>
<b>Version 1.1.0</b> <i>06 September 2022</i>	The version number for Modicon M580 that addresses these vulnerabilities has been updated from v4.01 to v4.02.
<b>Version 2.0.0</b> <i>11 October 2022</i>	A clarification was added to the list of affected products by splitting Modicon M580 and Modicon M580 Safety CPU ranges. The purpose of the notification update is to inform customers that the latest fix Modicon M580 v4.02 does not apply to the Safety range of M580. It is highly recommended that customers using Modicon M580 Safety ranges continue to implement the mitigations shared in this document.
<b>Version 3.0.0</b> <i>13 December 2022</i>	The Modicon M580 sv4.02 firmware has been retracted for quality issues and is no longer available for download. Additional mitigations have been introduced for Modicon M580 CPU and M580 CPU Safety, and we urge customers to deploy these mitigations to further reduce the risk of potential exploitation of identified vulnerabilities.
<b>Version 4.0.0</b> <i>14 March 2023</i>	Remediation for the Modicon M580 CPU is available for download.
<b>Version 5.0.0</b> <i>13 August 2024</i>	A remediation is available for the Modicon M580 CPU Safety ( <a href="#">page 2</a> ).