

Changelog

Table of Contents

1	Products affected.....	2
2	New firmware features	2
3	New hardware features	2
4	Issues fixed	2
5	Upgrade procedure.....	3

1 Products affected

Commercial reference	Product	FW version
LSS100100	Wiser for KNX	2.1.0
LSS100200	spaceLYnk	2.1.0

Table 1: Products affected

2 New firmware features

- Improved Cyber security
- homeLYnk logic controller is renamed to Wiser for KNX logic controller
- Force change of admin password
 - Admin is forced to change password before first login or in case of upgrade controller using default password (admin)
- Logging all authentication attempts
- Logging of read telegrams can be disabled

3 New hardware features

- HW 2.x.x - new processor ARM 7
- HW 2.x.x - reset button is located on front side

4 Issues fixed

- Settings of pulse metering in smartlink RTU / TCP error
 - Unable to save settings of Smartlink RTU / TCP when pulse meter is configured
- It is possible to change the login without entering a new password
 - This issue can break login of user
- Logging of bool object cause error in CSV export
 - Breaks data in CSV export

5 Upgrade procedure

1. Click *Configurator -> System -> System -> Upgrade firmware*
2. Find firmware for your product
3. Click **OK**

Note: It is highly recommended to create backup of your actual project before upgrade!

Note: Check HW version of you logic controller. There are available HW 1.xx and HW 2.xx in parallel on the market. HW version is located in the side label of the controller.