

Product: Logic controller “spaceLYnk”

Reference number: LSS100200

<i>Date of release</i>	<i>HWx.y or SWx.y.z version</i>	<i>Description of change to previous version</i>	<i>Linked documents</i>
2014-05-22	SW-1.0.0	Initial description	FW1_0_0-sl.img
2015-02-27	SW-1.1.0	See <i>Change_Log_spaceLYnk SW V1.1 & homeLYnk SW V1.3.docx</i>	spacelynk-1.1.0.img AR1796_EdB_User_Guide_spaceLYnk_EN.pdf
2015-06-05	HW-1.2	Upgrade of BCU TPUART2 from version 5.2 to version 5.3; solving "TP disconnected" issue, RN-2015-W23	
2015-05-18	SW-1.1.1	See <i>Change_Log_spaceLYnk SW V1.1.1 & homeLYnk SW V1.3.1.docx</i>	spacelynk-1.1.1.img
2016-04-20	SW-1.2.0	See <i>Change_Log_spaceLYnk SW V1.2.0 & homeLYnk SW V1.5.0.pdf</i>	spaceLYnk-1.2.0.img
2016-07-22	SW-1.2.1	See <i>Change_Log_spaceLYnk SW V1.2.1 & homeLYnk SW V1.5.1.pdf</i>	spaceLYnk-1.2.1.img
2016-10-21	HW-1.3*	Upgrade of PCB. Remove 10k resistor. Add capacitor 220n; solving “Failed start-ups of hL/sL” issue	Bill of Materials-LM2IMX280v2.1.xlsx, LM2IMX280v2.1.PDF
2016-12-16	HW-1.4*	Fixing of Ethernet LEDs	LM2IMX280v2.1.pdf LED_fix.pdf
2017-04-28	SW-2.0.0	See <i>Change_Log_spaceLYnk SW V2.0.0 & homeLYnk SW V2.0.0.pdf</i>	spaceLYnk-2.0.0.img
2017-06-27	SW-2.0.1	See <i>Change_Log_spaceLYnk SW V2.0.1 & homeLYnk SW V2.0.1.pdf</i>	spaceLYnk-2.0.1.img
2017-10-13	SW-2.1.0	See <i>Change_Log_spaceLYnk SW V2.1.0 & Wiser for KNX SW V2.1.0.pdf</i>	spaceLYnk-2.1.0_hw1.xx.img spaceLYnk-2.1.0_hw2.xx.img
2017-10-13	HW-2.0*	CPU upgrade, reset button from top side	
2018-01-09	SW-2.1.1	See <i>Change_Log_spaceLYnk SW V2.1.1 & Wiser for KNX SW V2.1.1.pdf</i>	spaceLYnk-2.1.1_hw1.xx.img spaceLYnk-2.1.1_hw2.xx.img
2018-08-03	HW-3.0*	New SPI flash chip, RAM and MCU	
2018-08-03	SW-2.3.0	See <i>Change_Log_spaceLYnk SW V2.3.0 & Wiser for KNX SW V2.3.0.pdf</i>	spaceLYnk-2.3.0_hw1.xx.img spaceLYnk-2.3.0_hw2.xx_hw3.xx.img

* non-public documents