

Versioning

for Wiser for KNX logic controller

LSS100100

Publication date 2020-07-08



| Date of release | HWx.y or SWx.y Version | Description of change to previous version | Linked documents |
|-----------------|------------------------------|--|---|
| 2013-6-25 | HW-1.0 SW-1.0 | First release after validation | 2013.06.25-hl.img |
| 2013-6-25_A | HW-1.0 SW-1.1 | New kernel for RS-485, Serial 3161XXX only | 2013.06.25_A-hl.img |
| 2014-01-29 | HW-1.1* | New isolators & DC/DC convertor | Homelynk EMC test.pdf 194300-012-2014.pdf 194300-010-2014 AJ.pdf Homelynk EMC test.pdf |
| 2014-02-25 | SW-1.2.0 | New fuctions, BACnet Server, etc. | FW1_2_0-hl.img |
| 2014-05-07 | SW-1.2.1 | New functions, bug fixes, etc | FW1_2_1-hl.img |
| 2015-02-27 | SW-1.3 | See Change_Log_spaceLYnk SW V1.1 & homeLYnk SW V1.3.docx | homelynk-1.3.0.img AR1740_EdC_User_Guide_ homeLYnk_EN.pdf |
| 2015-05-06 | HW-1.2 | Upgrade of BCU TPUART2 from version 5.2 to version 5.3; solving "TP disconnected" issue, RN-2015-W23 | |
| 2015-05-18 | SW-1.3.1 | See Change_Log_spaceLYnk SW V1.1.1 & homeLYnk SW V1.3.1.docx | homelynk-1.3.1.img |
| 2016-04-20 | SW-1.5.0 | See Change_Log_spaceLYnk SW V1.2.0 & homeLYnk SW V1.5.0.pdf | homeLYnk-1.5.0.img |
| 2016-07-22 | SW-1.5.1 | See Change_Log_spaceLYnk SW V1.2.1 & homeLYnk SW V1.5.1.pdf | homeLYnk-1.5.1.img |
| 2016-10-21 | HW-1.3* | Upgrade of PCB. Remove 10k resistor. Add capacitor 220n; solving "Failed start-ups of hL/sL" issue | Bill of Materi- als-LM2IMX280v2.1.xlsx, LM2IMX280v2.1.PDF |
| 2016-12-16 | HW-1.4* | Fixing of Ethernet LEDs | LM2IMX280v2.1.pdf LED_fix.pdf |
| 2017-04-28 | SW-2.0.0 | See Change_Log_spaceLYnk SW V2.0.0 & homeLYnk SW V2.0.0.pdf | homeLYnk-2.0.0.img |
| 2017-06-27 | SW-2.0.1 | See Change_Log_spaceLYnk SW V2.0.1 & homeLYnk SW V2.0.1.pdf | homeLYnk-2.0.1.img |
| 2017-10-13 | SW-2.1.0 | See Change_Log_spaceLYnk SW V2.1.0 & Wiser for KNX SW V2.1.0.pdf | Wiser_for_KNX-2.1.0_hw1.xx.img Wiser_for_KNX-2.1.0_hw2.xx.img |
| 2017-10-13 | HW-2.0* | CPU upgrade, reset button from top side | |
| 2018-01-09 | SW-2.1.1 | See Change_Log_spaceLYnk SW V2.1.1 & Wiser for KNX SW V2.1.1.pdf | Wiser_for_KNX-2.1.1_hw1.xx.img Wiser_for_KNX-2.1.1_hw2.xx.img |
| 2018-08-03 | HW-3.0 | New SPI flash chip, RAM and MCU | |
| 2018-08-03 | SW-2.3.0 | See Change_Log_spaceLYnk SW V2.3.0 & Wiser for KNX SW V2.3.0.pdf | Wiser_for_KNX-2.3.0_hw1.xx.img Wiser_for_KNX-2.3.0_hw2.xx_hw3.xx.img |
| 2019-01-xx | HW-3.1 | Industrial SD card | |
| 2019-07-25 | SW-2.4.0 | See Changelog_spaceLYnk SW V2.4.0 & Wiser for KNX SW V2.4.0.pdf | Wiser_for_KNX-2.4.0_hw1.xx.img Wiser_for_KNX-2.4.0_hw2.xx_hw3.xx.img |
| 2020-06-30 | SW-2.5.0 | See Changelog_spaceLYnk SW V2.5.0 & Wiser for KNX SW V2.5.0.pdf | Wiser_for_KNX-2.5.0_hw1.xx.img Wiser_for_KNX-2.5.0_hw2.xx_hw3.xx.img |
| 2020-07-08 | SW-2.5.1 | See Changelog_spaceLYnk SW V2.5.1 & Wiser for KNX SW V2.5.1.pdf | Wiser_for_KNX-2.5.1_hw1.xx.img Wiser_for_KNX-2.5.1_hw2.xx_hw3.xx.img |
| | | | |

