


AFDD



JYT3814601-00

05-2021



NOTICE

HAZARD OF WRONG INSULATION RESISTANCE TEST RESULT

In case of bottom feeding, disconnect the power supply wires from the bottom terminals before performing the insulation resistance test as per AS/NZS standards.

Failure to follow these instructions can result in wrong insulation resistance test result.