
## **Product Overview**

# Installation

MGE<sup>™</sup> Galaxy<sup>™</sup> 3500 and Smart-UPS<sup>®</sup> VT Parallel Maintenance Bypass Panel **Floor Mount** 45 kVA and 90 kVA 208 V



45 kVA and 90 kVA

Smart-UPS<sup>®</sup> VT 45 kVA and 90 kVA

### **IMPORTANT SAFETY INSTRUCTIONS** - SAVE THESE INSTRUCTIONS




Warning: ALL safety instructions in the Safety Sheet (990-2940) must be read, understood and followed when installing the UPS system. Failure to do so could result in equipment damage, serious injury, or death.



**Caution:** All electrical power and power control wiring must be installed by a qualified electrician, and must comply with local and national regulations for maximum power rating.



**Caution:** Operation and Maintenance must only be performed by qualified personnel.



Ð

Output neutral busbar

ч**ш**н Rear view

**R** 

PE/G



n

0

₿

Ð

Ø

6




990-3601A-001



6

Led indicators

90 kVA




Note: Refer to the UPS Receiving and Unpacking sheet (990-2940 for MGE Galaxy 3500 and 990-1747 for Smart-UPS VT) to determine the space requirements for the MBP. Consult local codes for any additional requirements. Ideally, install the MBP in a location close to the UPS.

# Level the Enclosure



Warning: The system must be installed on a level floor. The leveling feet will stabilize the enclosure, but will not account for a badly sloped floor.



- **1** Use a 13/14 mm wrench to adjust the four leveling feet.
- **2** Ensure that the system is level.



**Caution:** Do not move the enclosure after the leveling feet have been lowered.


# Floor Anchoring (if applicable)

#### Anchor the MBP enclosure to the floor



Note: Floor-anchoring bolts are not provided with the Maintenance Bypass Panel (MBP). Purchase the bolts locally (minimum size: M8). Follow the specifications given by the manufacturer when bolting the UPS system to the floor.

**1** Reuse the two transport brackets (one on each side) that were used to secure the UPS to the pallet during transport.



2 Drill two to six holes in the floor for each bracket. Attach with bolts.



For seismic applications, see the APC website for seismic requirements.

# **Prepare for Cables**



**Note:** All external cable connections with the UPS and mains must be made on-site. External cables are not supplied with the shipment.

**Note:** All control wire connections between the UPS and the MBP must be made on-site. Control wires (30 m) for MBP CAN I/O boards are supplied with the shipment.

### Create knockouts for cable access

#### **1**Remove the front panel.

**2**Remove the top

or bottom cover.

**B**Use a knockout punch to create appropriate-sized holes for the

cables/conduits in either the top or bottom cover of the MBP.

**4**Remove the left or right side panel.

**G**Remove the left or right inner panel.

**G**Install conduits (if applicable) and re-install all the covers.


**Run the Cables** 

only)

**1**Remove the

upper rear cover.


**2**Remove the top




- Remove the upper rear cover.
- **2**Run the cables through the top cover to the cable connection area.
- BRe-install the upper rear cover.

# Bottom

- **G**Re-install the I/O box.






Cable entry through the I/O box (UPS cables

top cover of the I/O box.

#### Top cable entry (input and output cables only)



#### cable entry (input and output cables only)

• Remove the upper rear cover.

**2**Remove the top cover of the I/O box.


**B**Remove the bottom cover of the I/O box.

A Remove the plate which blocks for cable access from the bottom.

SRoute the cables through the bottom to the cable connection area.

# **Connect Power Cables**


- Connect the UPS output from up to three UPS units (L1, L2, L3, N, G) to the UPS output terminals and the ground busbar.
- **2**Connect cables from the mains supply (L1, L2, L3, N, G) to the maintenance bypass terminals and the ground and input neutral busbars.
- **B**Connect cables from the critical load (L1, L2, L3, N, G) to the load terminals and the ground and output neutral busbars.




# **Connect Communication Cables**

Remove the bottom cover.

**2**Run the communication cables through the hole in the bottom front.



3 Connect the A-bus cables to X134A connectors on the MBP CAN I/O boards.



# **Specifications**

#### Electrical

- Voltage rating
- Wiring (only u
- Maximum cab
- Mains input ca
- UPS input cab
- System output
- UPS output ca

Warning: At 1

#### Physical

Dimensions  $(H \times W \times D)$ 

Weight

Shipping dime

Shipping weig

#### Environment

Operating envi

Operating tem

Humidity

**Torque value** 

Terminal block X002, X003, X

Terminal block X001, X005

Busbars M6

# **Contact Information**

contact.

	45 kVA	90 kVA	
5	208/220 V 4W+GND	208/220 V 4W+GND	
use copper conductors suitable for at least 75°C)			
ble size	4/0 AWG	2 x 4/0 AWG	
able	4/0 AWG	2 x 4/0 AWG	
ble	4 AWG	1 AWG	
t	4/0 AWG	2 x 4/0 AWG	
able	4 AWG	1 AWG	
100% switch mode load, the system neutral connections			

must be rated for 173% phase current.

	1487 x 352 x 837 mm (58.5 x 14 x 33 in)	1487 x 352 x 837 mm (58.5 x 14 x 33 in)	
	159 kg (350 lbs)	191 kg (420 lbs)	
ensions	1664 x 864 x 1219 mm (65.5 x 34 x 48 in)	1664 x 864 x 1219 mm (65.5 x 34 x 48 in)	
ght	194 kg (426 lbs)	225 kg (496 lbs)	
tal			
ironment	Indoor use only, protect from water and conductive contaminates		
perature	0° to 40°C (32° to 104°F)		
	0 to 95%, non-condensing		
ks X004	6.89 Nm (61 lb in)		
ks	25.7 Nm (192 lb in)		
	11.3 Nm (100 lbs in)		

For local, country-specific centers: go to www.apc.com/support/

### Appendix

#### Diagram

