

XUW firmware release note

Ref.: XUW Firmware update V1.7.22.1

Dear Sir or Madam,

Update of **XUW firmware version** available (compatible with the XUIW PC-software V1.7.10.1).
If you are using the previous PC software version V1.6.6.1, it should be updated by the V1.7.10.1 version (see web site link here-under)

The firmware can be updated via XUWFind (PC software).

- ⇒ **New XUW firmware version:** V1.7.22.1 (Sensor Date Code 2014w22)
- ⇒ **Previous XUW firmware version:** V1.7.21.1 (Sensor Date Code 2013w49)

Improvements in Firmware V1.7.22.1:

- ⇒ **EtherNet/IP**
 - First 4 bytes in EtherNet/IP protocol are missing. Issue is only in version 1.7.21.1. This was not an issue in earlier versions
- ⇒ **Update of system files**
 - System files of operating system were updated. No functional changes in XUW firmware.

Please contact us for any further product information you may need.

Download-Links:

XUW Firmware V1.7.22.1 (17 MByte):

<http://www.tesensors.com/products/osisense-xuw?docType=1555893&title=Firmware – Released>

XUW Release history:

- ⇒ PC: V1.7.10.1 Firmware: V1.7.22.1
- ⇒ PC: V1.7.10.1 Firmware: V1.7.21.1 (Date Code 2013w49)
- ⇒ PC: V1.6.6.1 Firmware: V1.6.5.2 (initial release)