

# Release notes

Product name: Xflow

Version number: 4.0.5.0

Language: EN



Date: 03th Dec, 2014

Written by: **Schneider Electric Telecontrol**

Checked by: **Schneider Electric Telecontrol**

Toutes les informations contenues dans ce document sont la propriété exclusive de Schneider Electric Telecontrol S.A.S. Elles ne peuvent être divulguées ou utilisées sans notre accord écrit préalable.  
All the information contained in this document is the exclusive property of Schneider Electric Telecontrol S.A.S. It may not be revealed or used without our prior written consent.

**Summary**

<b>1.</b>	<b>Introduction .....</b>	<b>3</b>
<b>2.</b>	<b>Warning .....</b>	<b>3</b>
<b>3.</b>	<b>Description of the version .....</b>	<b>3</b>
<b>4.</b>	<b>Bug tracking list .....</b>	<b>3</b>
1.1	#9204 - Case 13906092 - Broken link / missing page in 14DIO direct access page for Air Liquide profile.	3
1.2	#9221 - Case 14420956 - Problem with APN password encryption .....	3
1.3	#9213: Error on GSM modem connection when using code pin.....	3
1.4	#9148: Case 12680092 – Stration PID function was not working.....	4
1.5	#9223: Status of variables in the dashboards .....	4
1.6	#9249, #9186: Case 14912542 - Specific images for Water Pump Station synoptics were missing .....	4
1.7	#9250: Case 14912542 - Modifications on pump configuration are impossible .....	4

Toutes les informations contenues dans ce document sont la propriété exclusive de Schneider Electric Telecontrol S.A.S. Elles ne peuvent être divulguées ou utilisées sans notre accord écrit préalable.  
 All the information contained in this document is the exclusive property of Schneider Electric Telecontrol S.A.S. It may not be revealed or used without our prior written consent.

## 1. Introduction

---

**Document scope**      **This document describes the Xflow version 4.0.5.0**

---

**Application field**      **This Xflow version applies on iRIO, XLRIO and PC**

---

**Comments**              **The version 4.0.5.0 available since 03/12/2014**

---

## 2. Warning

N/A

## 3. Description of the version

The version 4.0.5.0 fixes some issues. Those issues are identified by a “Bug tracker ID”.

## 4. Bug tracking list

### 1.1 #9204 - Case 13906092 - Broken link / missing page in 14DIO direct access page for Air Liquide profile

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: there were some errors in 14DIO and 16DIO direct access pages with Air Liquide profile.

### 1.2 #9221 - Case 14420956 - Problem with APN password encryption

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: RAS connection didn't works after an iRio reset when using a password for connection APN.

### 1.3 #9213: Error on GSM modem connection when using code pin

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: GSM modem connection didn't works after a modem re-initialisation when using a PIN code for SIM card.

Toutes les informations contenues dans ce document sont la propriété exclusive de Schneider Electric Telecontrol S.A.S. Elles ne peuvent être divulguées ou utilisées sans notre accord écrit préalable.

All the information contained in this document is the exclusive property of Schneider Electric Telecontrol S.A.S. It may not be revealed or used without our prior written consent.

#### **1.4 #9148: Case 12680092 – Stration PID function was not working**

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: Stration PID function was not working.

#### **1.5 #9223: Status of variables in the dashboards**

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: During the refresh time on a dashboard, the error status on a variable may appear but it never disappears whereas its status is back to normal.

#### **1.6 #9249, #9186: Case 14912542 - Specific images for Water Pump Station synoptics were missing**

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: Specific images for Water Pump Station synoptics were missing.

#### **1.7 #9250: Case 14912542 - Modifications on pump configuration are impossible**

This issue appeared with version 4.0.1.0, it doesn't exist on previous version.

Problem was: It was impossible to modify values set for the parameters of a pump.