

Metered Rack Power Distribution Unit Online Guide Addendum

Control console

Serial and Telnet interfaces may show outlet current management and erroneous current measurements for several outlets (15 or 18, depending on the Metered Rack Power Distribution Unit (PDU) and version of the firmware). These Rack PDUs should show only current management for six banks of outlets. This issue will be resolved in firmware version 3.5.7 and will be available on the APC Web site, www.apc.com. For accurate bank representation, use the Rack PDU Web interface until firmware version 3.5.7 is installed on your Rack PDU.

Perform a firmware upgrade

For more information on how to download and transfer firmware to the Metered Rack PDU, see the Metered Rack PDU *User's Guide*, on the enclosed *Utility CD*.

Customer support and warranty information is available at the APC Web site, www.apc.com.

© 2008 American Power Conversion. All rights reserved. All APC trademarks are property of American Power Conversion. Other trademarks are property of their respective owners.



990-3343
02/2008

