Schneider Electric Easy UPS Online Monitoring Software v2.6-GS-01-23116 Release Notes

The Schneider Electric Easy UPS Online Monitoring Software v2.5-GS-01-23116 release notes apply to the **APVS9601 Easy UPS Online SNMP Card**, and the Easy UPS Online over serial and USB communications.

New Features

Top ↑

New Feature
OpenJDK Update The OpenJDK version bundled with the software is 17.0.4.

Fixed Issues

Top ↑

Fixed Issue
The software is now compatible with Windows 10, Windows 11, Windows Server 2016, Windows Server 2019, and Windows Server 2022.
Multiple vulnerabilities reported in the security notification published here & general security related improvements.
General security related improvements

Known Issues

Known Issue
You cannot use the special character "-" in the **SMTP ID** and **Email ID** fields in the **Email Configuration** screen.
The **Purchase Information** screen does not display any data.
The **Default** button in the **Parameter Settings** screen does not work as expected.
The "Battery disconnected" event is not corrected logged in the **Events Action** screen and the **Messages** window. **NOTE:** This issue is only seen with SNMP.
SRV10KUXI, SRV15KUXI, and SRV20KUXI UPS devices do not enter bypass mode when the output power is off when **Bypass when UPS is off** is enabled in the **Parameter Settings** screen. Workaround: Power off the UPS device before enabling **Bypass when UPS is off**.
The **Battery current** for SRV10KUXI, SRV15KUXI, SRV20KUXI, 1KRIL, 2KUXI, and 3KRIL UPS devices is incorrectly displayed as 0.0 Amps in the **Status Diagram** screen.
After a successful self test, the "Battery self test passed" event is not logged to the Event Log. This issue affects SRV10KUXI, SRV15KUXI, and SRV20KUXI UPS devices.
Systray icon turns grey after several hours of communication, while the background UPS service continues to run and remains responsive.

https://www.apc.com

06-2023