

INTEGRITY VERIFICATION PROCEDURE

Integrity Verification of the Modicon M580 CPU SV04.20 files (.sedp)

“Important notes”

(1) Reach out to our customer care team in your location if you face any difficulty with the download

Before the Software Installation

Before using the provided content, we recommend checking the integrity of the software downloaded from the Schneider Electric website.

To verify the integrity of the downloaded files (.sedp) of Modicon M580 CPU SV04.20, proceed as follows:

- Launch any SHA256 generator tool.
- Generate the SHA256 checksum value for the Modicon M580 CPU SV04.20, (.sedp) file.
- If the generated value matches with the value provided in the Checksum List, you can proceed with the installation.
- If they do not match, download the Modicon M580 CPU SV04.20, (.sedp) again and repeat the procedure until both checksum values match (1).

Checksum List

BMEH582040_v04.20.15.sedp	1beba081c5e2c9a7b652ea32db39ac440982c8910e96502d17511e8cc1f02a4f
BMEH584040_v04.20.15.sedp	342226f1843adc69ea478e37ca5e2c3104c22ae12507b9275cd7cf2f1c581d62
BMEH586040_v04.20.15.sedp	2d96e8f466fcec3d54cf6dba71c5a0eae81563b8f662aaffcaf9a3b21874e22d
BMEP581020_v04.20.15.sedp	5def83ae5b20ddd478cb2009e2bbe9b699c5a5fabd147af0e28d305b0a2319c0
BMEP582020_v04.20.15.sedp	da49ef5e46e9415bc4606134e2a292b06689dfe2983cf976fd45186fc9bf351d
BMEP582040_v04.20.15.sedp	252e9911a3258df6f2d9c5c2b49bdfb913b09085adc8a79ea9f22e51247b4d2d
BMEP583020_v04.20.15.sedp	10dac9d94ff285edae39d6dd25db6e0f3cfa8630405179328e8f9e8b3fccc18c
BMEP583040_v04.20.15.sedp	70d597ffb0b5e4d656a0e252b9664cfedcc423394afb77381cb896f5d49a0249

BMEP584020_v04.20.15.sedp	4a7fff21f25cc536581a5ef25fcf92f66481ac9753d8f83fbf8935c066559f5a
BMEP584040_v04.20.15.sedp	f7eb7f05e5f4a86cd6f6ab393e3b6454c3809a4f2a88c4ba3ef23215038e08ed
BMEP585040_v04.20.15.sedp	5cdb34a4f507b7e557903da7c891498e1bbf12eaa458de90a410792d087dded4
BMEP586040_v04.20.15.sedp	dab860fc40853e27919796678551532bcc4b3a2e26e9fa18ad79ad50b8433a9d