

Changelog

for controllers spaceLYnk, Wiser for KNX

Firmware version: 2.6.2

LSS100100, LSS100200

Publication date: 2021-08-30



Table of Contents

1	Products affected.....	5
2	U.Motion Compatibility.....	5
3	Changes	6
3.1	Added	6
3.2	Changed	6
3.3	Security.....	6
4	Upgrade procedure.....	7

1 Products affected

Commercial reference	Product	FW version
LSS100100	Wiser for KNX	2.6.1
LSS100200	spaceLYnk	2.6.1

2 U.Motion Compatibility

If the Wiser for KNX or spaceLYnk Controller is used together with a U.Motion Touch Panel in the installation, please check the compatibility table below **before** proceeding with the FW upgrade in the controllers. The FW from 2.5.X in Wiser for KNX and spaceLYnk includes the new Touch 3.0 visualization with several new features. This new visualization has minimum browser requirements and **it's not fully supported by all U.Motion client Touch Panels.**

Please check the Commercial Reference, Serial Number and OS System in your device and compare it with the following table:

Touch Panel Client	Commercial References	OS Version	Selling Date		Serial Number		Touch 3.0 Compatibility	Observation
			Start	End	Start	End		
U. Motion 7" V2/V3	MEG6260-0307 MTN6260-0307	Android 6	Oct-18	ongoing	S3002702	ongoing	Supported	Please update the Touch Panel with the latest FW "Android 6.0 v2" available in the U.Motion Software & Firmware download section in se.com and merten.de
U. Motion 7" V2		Android 4.2	May-2016	Sep-2018	S3000605	S3002701	Not supported	The browser in the Touch Panels doesn't meet the minimum requirements to fully support the new Touch 3.0 visualization. Schneider Electric recommends using the Touch 2.0 visualization together with these Touch Panels instead. Note: If a downgrade from Touch 3 to Touch 2 is required, please contact Customer Care.
U. Motion 7" V1		Android 2.3	May-2014	Feb-2016	S3000001	S3000602		
Touch Panel Client	Commercial References	OS Version	Selling Date		Serial Number		Touch 3.0 Compatibility	Observation
			Start	End	Start	End		
U. Motion 10" & 15" v2	MEG6260-0310 MTN6260-0310 MEG6260-0315 MTN6260-031	Linux	Jun-2017	ongoing	S2001482	ongoing	Will be supported (with some considerations)	To support the new Touch 3.0 visualization, the browser and the FW in the Touch Panels must be updated to a version higher than 1.3.4. Please contact your Customer Care for assistance.
U. Motion 10" & 15" v1		Linux	May-2014	June 2017	S2000001	S2001481		

3 Changes

3.1 Added

3.2 Changed

- bacnet client library: add support for accumulator object type
- scenes: fix scene control for scenes without a mapped object
- applications: fix applications sorting for applications without title
- applications: fix public directory access rights
- visualization: do not apply scale(1) to elements that have scaling set to 100%
- modbus: add profile validation during upload
- flashsys: add version tag to prevent caching issues
- trends: minor fixes for small screens
- system config: add CORS origin settings for the HTTP server
- trends: highlight active trend in the legend when the tooltip is shown

3.3 Security

- CORS – cross-origin resource sharing configuration. Up to 4 IP addresses / hosts which can use CORS.

4 Upgrade procedure

1. **Click** *Configurator -> System -> System -> Upgrade firmware*
2. **Find** firmware for your product
3. **Click** OK



Note: It is highly recommended to create backup of your actual project before upgrade!



Note: We recommend to use always the latest firmware because of optimization of writing data to microSD cards, running services, cyber security etc.



Note: Check HW version of your logic controller. There are available HW 1.xx, HW 2.xx and HW 3.xx in parallel on the market. HW version is located in the side label of the controller.

Schneider Electric

35 rue Joseph Monier

92500 Rueil Malmaison – France

Phone: +33 (0) 1 41 29 70 00

www.schneider-electric.com

© 2014-2021 Schneider Electric. All rights reserved.



This document has been
printed on recycled paper.