

# Versioning

## for Wiser for KNX logic controller

LSS100100

Publication date 2021-04-29



Date of release	HWx.y or SWx.y Version	Description of change to previous version	Linked documents
2013-6-25	HW-1.0 SW-1.0	First release after validation	2013.06.25-hl.img
2013-6-25_A	HW-1.0 SW-1.1	New kernel for RS-485, Serial 3161XXX only	2013.06.25_A-hl.img
2014-01-29	HW-1.1*	New isolators & DC/DC convertor	Homelynk EMC_test.pdf 194300-012-2014.pdf 194300-010-2014 AJ.pdf Homelynk EMC_test.pdf
2014-02-25	SW-1.2.0	New fuctions, BACnet Server, etc.	FW1_2_0-hl.img
2014-05-07	SW-1.2.1	New functions, bug fixes, etc	FW1_2_1-hl.img
2015-02-27	SW-1.3	See Change_Log_spaceLYnk SW V1.1 & homeLYnk SW V1.3.docx	homelynk-1.3.0.img AR1740_EdC_User_Guide_ homeLYnk_EN.pdf
2015-05-06	HW-1.2	Upgrade of BCU TPUART2 from version 5.2 to version 5.3; solving "TP disconnected" issue, RN-2015-W23	
2015-05-18	SW-1.3.1	See Change_Log_spaceLYnk SW V1.1.1 & homeLYnk SW V1.3.1.docx	homelynk-1.3.1.img
2016-04-20	SW-1.5.0	See Change_Log_spaceLYnk SW V1.2.0 & homeLYnk SW V1.5.0.pdf	homeLYnk-1.5.0.img
2016-07-22	SW-1.5.1	See Change_Log_spaceLYnk SW V1.2.1 & homeLYnk SW V1.5.1.pdf	homeLYnk-1.5.1.img
2016-10-21	HW-1.3*	Upgrade of PCB. Remove 10k resistor. Add capacitor 220n; solving "Failed start-ups of hL/sL" issue	Bill of Materi- als-LM2IMX280v2.1.xlsx, LM2IMX280v2.1.PDF
2016-12-16	HW-1.4*	Fixing of Ethernet LEDs	LM2IMX280v2.1.pdf LED_fix.pdf
2017-04-28	SW-2.0.0	See Change_Log_spaceLYnk SW V2.0.0 & homeLYnk SW V2.0.0.pdf	homeLYnk-2.0.0.img
2017-06-27	SW-2.0.1	See Change_Log_spaceLYnk SW V2.0.1 & homeLYnk SW V2.0.1.pdf	homeLYnk-2.0.1.img
2017-10-13	SW-2.1.0	See Change_Log_spaceLYnk SW V2.1.0 & Wiser for KNX SW V2.1.0.pdf	Wiser_for_KNX-2.1.0_hw1.xx.img Wiser_for_KNX-2.1.0_hw2.xx.img
2017-10-13	HW-2.0*	CPU upgrade, reset button from top side	
2018-01-09	SW-2.1.1	See Change_Log_spaceLYnk SW V2.1.1 & Wiser for KNX SW V2.1.1.pdf	Wiser_for_KNX-2.1.1_hw1.xx.img Wiser_for_KNX-2.1.1_hw2.xx.img
2018-08-03	HW-3.0	New SPI flash chip, RAM and MCU	
2018-08-03	SW-2.3.0	See Change_Log_spaceLYnk SW V2.3.0 & Wiser for KNX SW V2.3.0.pdf	Wiser_for_KNX-2.3.0_hw1.xx.img Wiser_for_KNX-2.3.0_hw2.xx_hw3.xx.img
2019-01-xx	HW-3.1	Industrial SD card	
2019-07-25	SW-2.4.0	See Changelog_spaceLYnk SW V2.4.0 & Wiser for KNX SW V2.4.0.pdf	Wiser_for_KNX-2.4.0_hw1.xx.img Wiser_for_KNX-2.4.0_hw2.xx_hw3.xx.img
2020-06-30	SW-2.5.0	See Changelog_spaceLYnk SW V2.5.0 & Wiser for KNX SW V2.5.0.pdf	Wiser_for_KNX-2.5.0_hw1.xx.img Wiser_for_KNX-2.5.0_hw2.xx_hw3.xx.img
2020-07-08	SW-2.5.1	See Changelog_spaceLYnk SW V2.5.1 & Wiser for KNX SW V2.5.1.pdf	Wiser_for_KNX-2.5.1_hw1.xx.img Wiser_for_KNX-2.5.1_hw2.xx_hw3.xx.img

2021-01-21	SW-2.6.0	See Changelog_spaceLYnk SW V2.6.0 & Wiser for KNX SW V2.6.0.pdf	Wiser_for_KNX-2.6.0_hw1.xx.img Wiser_for_KNX-2.6.0_hw2.xx_hw3.xx.img
2021-04-29	SW-2.6.1	See Changelog_spaceLYnk SW V2.6.1 & Wiser for KNX SW V2.6.1.pdf	Wiser_for_KNX-2.6.1_hw1.xx.img Wiser_for_KNX-2.6.1_hw2.xx_hw3.xx.img
2021-08-30	SW-2.6.2	See Changelog_spaceLYnk SW V2.6.2 & Wiser for KNX SW V2.6.2.pdf	Wiser_for_KNX-2.6.2_hw1.xx.img Wiser_for_KNX-2.6.2_hw2.xx_hw3.xx.img