

Versioning

for spaceLYnk logic controller

LSS100200

Publication date 2026-03-16



Date of release	HWx.y or SWx.y Version	Description of change to previous version	Linked documents
2014-05-22	SW-1.0.0	Initial description	FW1_0_0-sl.img
2015-02-27	SW-1.1.0	See Change_Log_spaceLYnk SW V1.1 & homeLYnk SW V1.3.docx	spacelynk-1.1.0.img AR1796_EdB_User_Guide_ spaceLYnk_EN.pdf
2015-06-05	HW-1.2	Upgrade of BCU TPUART2 from version 5.2 to version 5.3; solving "TP disconnected" issue, RN-2015-W23	
2015-05-18	SW-1.1.1	See Change_Log_spaceLYnk SW V1.1.1 & homeLYnk SW V1.3.1.docx	spacelynk-1.1.1.img
2016-04-20	SW-1.2.0	See Change_Log_spaceLYnk SW V1.2.0 & homeLYnk SW V1.5.0.pdf	spaceLYnk-1.2.0.img
2016-07-22	SW-1.2.1	See Change_Log_spaceLYnk SW V1.2.1 & homeLYnk SW V1.5.1.pdf	spaceLYnk-1.2.1.img
2016-10-21	HW-1.3*	Upgrade of PCB. Remove 10k resistor. Add capacitor 220n; solving "Failed start-ups of hL/sL" issue	Bill of Materi- als-LM2IMX280v2.1.xlsx, LM2IMX280v2.1.PDF
2016-12-16	HW-1.4*	Fixing of Ethernet LEDs	LM2IMX280v2.1.pdf LED_fix.pdf
2017-04-28	SW-2.0.0	See Change_Log_spaceLYnk SW V2.0.0 & homeLYnk SW V2.0.0.pdf	spaceLYnk-2.0.0.img
2017-06-27	SW-2.0.1	See Change_Log_spaceLYnk SW V2.0.1 & homeLYnk SW V2.0.1.pdf	spaceLYnk-2.0.1.img
2017-10-13	SW-2.1.0	See Change_Log_spaceLYnk SW V2.1.0 & Wisser for KNX SW V2.1.0.pdf	spaceLYnk-2.1.0_hw1.xx.img spaceLYnk-2.1.0_hw2.xx.img
2017-10-13	HW-2.0*	CPU upgrade, reset button from top side	
2018-01-09	SW-2.1.1	See Change_Log_spaceLYnk SW V2.1.1 & Wisser for KNX SW V2.1.1.pdf	spaceLYnk-2.1.1_hw1.xx.img spaceLYnk-2.1.1_hw2.xx.img
2018-08-03	HW-3.0	New SPI flash chip, RAM and MCU	
2018-08-03	SW-2.3.0	See Change_Log_spaceLYnk SW V2.3.0 & Wisser for KNX SW V2.3.0.pdf	spaceLYnk-2.3.0_hw1.xx.img spaceLYnk-2.3.0_hw2.xx_hw3.xx.img
2019-01-xx	HW-3.1	Industrial SD card	
2019-07-25	SW-2.4.0	See Changelog_spaceLYnk SW V2.4.0 & Wisser for KNX SW V2.4.0.pdf	spaceLYnk-2.4.0_hw1.xx.img spaceLYnk-2.4.0_hw2.xx_hw3.xx.img
2020-06-30	SW-2.5.0	See Changelog_spaceLYnk SW V2.5.0 & Wisser for KNX SW V2.5.0.pdf	spaceLYnk-2.5.0_hw1.xx.img spaceLYnk-2.5.0_hw2.xx_hw3.xx.img
2020-07-08	SW-2.5.1	See Changelog_spaceLYnk SW V2.5.1 & Wisser for KNX SW V2.5.1.pdf	spaceLYnk-2.5.1_hw1.xx.img spaceLYnk-2.5.1_hw2.xx_hw3.xx.img
2021-01-21	SW-2.6.0	See Changelog_spaceLYnk SW V2.6.0 & Wisser for KNX SW V2.6.0.pdf	spaceLYnk-2.6.0_hw1.xx.img spaceLYnk-2.6.0_hw2.xx_hw3.xx.img
2021-04-29	SW-2.6.1	See Changelog_spaceLYnk SW V2.6.1 & Wisser for KNX SW V2.6.1.pdf	spaceLYnk-2.6.1_hw1.xx.img spaceLYnk-2.6.1_hw2.xx_hw3.xx.img
2021-08-30	SW-2.6.2	See Changelog_spaceLYnk SW V2.6.2 & Wisser for KNX SW V2.6.2.pdf	spaceLYnk-2.6.2_hw1.xx.img spaceLYnk-2.6.2_hw2.xx_hw3.xx.img
2021-12-15	SW-2.7.0	See Changelog_spaceLYnk SW V2.7.0 & Wisser for KNX SW V2.7.0.pdf	spaceLYnk-2.7.0_hw1.xx.img spaceLYnk-2.7.0_hw2.xx_hw3.xx.img
2021-12-15	HW-3.2	Added Security chip U1 SE050C2HQ1/Z01SDZ	

2022-09-30	SW-2.8.0	See Changelog_spaceLYnk SW V2.8.0 & Wisser for KNX SW V2.8.0.pdf	spaceLYnk-2.8.0_hw1.xx.img spaceLYnk-2.8.0_hw2.xx_hw3.xx.img
2023-05-30	SW-2.8.2	See Changelog_spaceLYnk SW V2.8.2 & Wisser for KNX SW V2.8.2.pdf	spaceLYnk-2.8.2_hw1.xx.img spaceLYnk-2.8.2_hw2.xx_hw3.xx.img
2023-06-16	SW-2.8.3	See Changelog_spaceLYnk SW V2.8.3 & Wisser for KNX SW V2.8.3.pdf	spaceLYnk-2.8.3_hw1.xx.img spaceLYnk-2.8.3_hw2.xx_hw3.xx.img
2024-01-03	SW-3.0.0	See Changelog_spaceLYnk SW V3.0.0 & Wisser for KNX SW V3.0.0.docx	spaceLYnk-3.0.0_hw1.xx.img spaceLYnk-3.0.0_hw2.xx_hw3.xx.img
2026-03-16	SW-3.1.0	See Changelog_spaceLYnk SW V3.1.0 & Wisser for KNX SW V3.1.0.docx	spaceLYnk-3.1.0_hw2.xx_hw3.xx.img

