
SPD NHA43714-01 05-2021



SPE

NOTICE

HAZARD OF PRODUCT DAMAGE DURING INSULATION RESISTANCE TEST

The SPD device must be disconnected before performing the insulation resistance test.

Failure to follow these instructions can

Failure to follow these instructions can result in equipment damage.