



PowerLogic™ PM5570, PM5650, PM5660 & PM5760 Firmware Revision History

Summary of Firmware Releases (Public) for PowerLogic™ PM5650

Release Version	Date	Reset System	Download System	Operating System	Language File	FPGA System	Comms System	Firmware Upgrade Method	Upgrade File Name
2.11.2	Oct-2020	2.11.2	N/A	2.11.2	2.18.0	2.0.3	2.11.2	FTP	PM5650_upgrade_V2.11.2_Release
2.10.1	Mar-2020	2.10.1	N/A	2.10.1	2.18.0	2.0.3	2.10.1	FTP	PM5650_upgrade_V2.10.1_Release

Version Number	Changes Since Version:	Description of Changes
2.11.2	2.10.1	<div><div>New Feature</div><ul style="list-style-type: none">OS Firmware checksum readable over HMI, and via Modbus Register 20533<div>Fixed Defect</div><ul style="list-style-type: none">Affecting zero-day vulnerabilities from "Ripple20" in low-level TCP/IP software library developed by Treck, Inc.- FixedBACnet setting not working when the deice ID is 0 - FixedBBMD IP 0.0.0.0 Not accepted in commands even BBMD disabled – FixedHTTP port number value is reset to default value after changed using Modbus commands - Fixed</div>
2.10.1	<ul style="list-style-type: none">None	<ul style="list-style-type: none">Initial Firmware release



Summary of Firmware Releases (Public) for PowerLogic™ PM5570

Release Version	Date	Reset System	Download System	Operating System	Language File	FPGA System	Comms System	Analog Input Measurement System	Firmware Upgrade Method	Upgrade File Name
3.1.3	Oct-2020	3.1.3	N/A	3.1.3	2.18.0	2.0.3	3.1.3	3.0.0	FTP	PM5570_Upgrade_V3.1.3_Release
3.1.0	Mar-2020	3.1.0	N/A	3.1.0	2.18.0	2.0.3	3.1.0	3.0.0	FTP	PM5570_Upgrade_V3.1.0_Release

Version Number	Changes Since Version:	Description of Changes
3.1.3	3.1.0	<div><div>New Feature</div><ul style="list-style-type: none">OS Firmware checksum readable over HMI, and via Modbus Register 20533<div>Fixed Defect</div><ul style="list-style-type: none">Affecting zero-day vulnerabilities from "Ripple20" in low-level TCP/IP software library developed by Treck, Inc.- FixedBACnet setting not working when the deice ID is 0 - FixedBBMD IP 0.0.0.0 Not accepted in commands even BBMD disabled – FixedHTTP port number value is reset to default value after changed using Modbus commands - Fixed</div>
3.1.0	None	<ul style="list-style-type: none">Initial Firmware release



Summary of Firmware Releases (Public) for PowerLogic™ PM5660

Release Version	Date	Reset System	Download System	Operating System	Language File	FPGA System	Comms System	Residual Current Measurement System	Firmware Upgrade Method	Upgrade File Name
3.1.3	Oct-2020	3.1.3	N/A	3.1.3	2.18.0	2.0.3	3.1.3	3.0.0	FTP	PM5660_Upgrade_V3.1.3_Release
3.1.1	Mar-2020	3.1.1	N/A	3.1.1	2.18.0	2.0.3	3.1.1	3.0.0	FTP	PM5660_Upgrade_V3.1.1_Release

Version Number	Changes Since Version:	Description of Changes
3.1.3	3.1.1	<div><div>New Feature</div><ul style="list-style-type: none">OS Firmware checksum readable over HMI, and via Modbus Register 20533<div>Fixed Defect</div><ul style="list-style-type: none">Affecting zero-day vulnerabilities from "Ripple20" in low-level TCP/IP software library developed by Treck, Inc.- FixedBACnet setting not working when the deice ID is 0 - FixedBBMD IP 0.0.0.0 Not accepted in commands even BBMD disabled – FixedHTTP port number value is reset to default value after changed using Modbus commands - Fixed</div>
3.1.1	None	<ul style="list-style-type: none">Initial Firmware release



Summary of Firmware Releases (Public) for PowerLogic™ PM5760

Release Version	Date	Reset System	Download System	Operating System	Language File	FPGA System	Comms System	Residual Current Measurement System	Firmware Upgrade Method	Upgrade File Name
3.1.3	Oct-2020	3.1.3	N/A	3.1.3	2.18.0	2.0.3	3.1.3	3.0.0	FTP	PM5760_Upgrade_V3.1.3_Release
3.1.1	Mar-2020	3.1.1	N/A	3.1.1	2.18.0	2.0.3	3.1.1	3.0.0	FTP	PM5760_Upgrade_V3.1.1_Release

Version Number	Changes Since Version:	Description of Changes
3.1.3	3.1.1	<p>New Feature</p> <ul style="list-style-type: none">OS Firmware checksum readable over HMI, and via Modbus Register 20533 <p>Fixed Defect</p> <ul style="list-style-type: none">Affecting zero-day vulnerabilities from "Ripple20" in low-level TCP/IP software library developed by Treck, Inc.- FixedBACnet setting not working when the deice ID is 0 - FixedBBMD IP 0.0.0.0 Not accepted in commands even BBMD disabled – FixedHTTP port number value is reset to default value after changed using Modbus commands - Fixed
3.1.1	None	<ul style="list-style-type: none">Initial Firmware release



NOTES:

Firmware version numbering system:
xx.yy.tttt

Per CR34
xx = Major (Hardware changes, etc.)
yy = Minor (feature add, etc.)
tttt = Quality (bug fixes, etc.)