
APC [™] Smart-UPS [™] Ultra Battery Pack **Extension Cable SRTL016**

Package Contents



Installation

CAUTION


RISK OF ELECTRIC SHOCK

- Do not connect the XLBP extension cable to the UPS/XLBP till the interconnection bracket is installed.
- Remove the interconnection bracket only after disconnecting the connector from the UPS/XLBP.

Failure to follow these instructions can result in minor or moderate injury and equipment damage.

NOTE: UPS model SRTL5KRM2Ux is used for purpose of illustration. The installation steps remain the same for SRTL8KRM4Ux and SRTL10KRM4Ux.

Single XLBP



Schneider Electric 35 rue Joseph Monier 92500 Rueil Malmaison - France

Phone: +33 (0) 1 41 29 70 00


www.apc.com

As standards, specifications, and design change from time to time, please ask for confirmation of the information given in this publication.

© 2023 Schneider Electric.All rights reserved.



Multiple XLBPs



2 EN TME26184 – 06/2023