

Version: UPS 17.0(SMC)

Applicable SKUs:

=====

ID 1028, All standard SKUs beginning with SMC prefixes.

SMC: SMC1000C, SMC1000RM2UC, SMC1500C, SMC1500RM2UC, SMC1000IC, SMC1000I-2UC,  
SMC1500IC, SMC1500I-2UC

This revision revives the communication of the USB port while the UPS is on "suspend" mode when the PCBE starts recommunicating.

Change logs:

1. Increase the detection of the USB D- signal to escape the "suspended"

Note: Smart-UPS Firmware Upgrade Wizard tool

always includes the latest released firmware and helps upgrade the UPS code.

Link to tool - <https://www.apc.com/us/en/faqs/FA279197/>

Version: UPS 16.5(SMC)

Applicable SKUs:

=====

ID 1028, All standard SKUs beginning with SMC prefixes.

SMC: SMC1000C, SMC1000RM2UC, SMC1500C, SMC1500RM2UC, SMC1000IC, SMC1000I-2UC,  
SMC1500IC, SMC1500I-2UC

This revision provides stronger network data security protection via the below mechanisms, to prevent malicious firmware from being upgraded to the UPS through communication interface ports (including RJ45).

Change logs:

1. The mechanism of firmware signing adds to the code in order to protect the UPS from malicious firmware spoofs. Based on the above, firmware upgrade via NMC is re-enabled. (model-dependent)
2. Added the selection of "Firmware Update Interface" under LCD Menu->Configuration. This helps users decide whether to allow performing firmware upgrades through the communication ports. The icon indicates "FU.1" to enable all interface communication ports, and "FU.0" to disable all ports. "FU.2" is set by the communication application.
3. Changed TLS used for SmartConnect to the MbedTLS for cybersecurity.

Note: Smart-UPS Firmware Upgrade Wizard tool

always includes the latest released firmware and helps upgrade the UPS code via serial(RS232) port; Upgrade via USB port from this tool is not recommended.

Link to tool - <https://www.apc.com/us/en/faqs/FA279197/>

Initial Released Version: UPS 16.0

Compatibility:

=====

AP9613 Dry Contact Version Next Gen Relay IO card 2.1

AP9620 LCC Version 3.0

AP9624 (Second Gen Interface Expander Card) v1.0X

AP9631/AP9630 card APP SUMX 6.2.1, AOS 6.2.1

AP9635 CH / AP9631card APP SUMX 6.4.6, AOS 6.4.6

AP9635 CH card APP SUMX 6.4.0, AOS 6.4.0

PowerChute Business Edition v9.2

FUW (Firmware Upgrade Wizard) Tool v4.2.1