

Version: UPS 02.0(SMC)

Applicable SKUs:

=====

ID 1061, All standard SKUs beginning with SMC prefixes.

SMC: SMC1000C, SMC1000-2UC, SMC1000IC, SMC1000I-2UC, SMC1500C, SMC1500-2UC, SMC1500IC, SMC1500I-2UC

This revision provides stronger network data security protection via the below mechanisms to prevent malicious firmware from being upgraded to the UPS through communication interface ports (including RJ45).

Change logs:

1. Changed TLS used for SmartConnect to MbedTLS for cybersecurity.

Note: Smart-UPS Firmware Upgrade Wizard tool

always includes the latest released firmware and helps upgrade the UPS code via serial(RS232) port; Upgrade via USB port from this tool is not recommended.

Link to tool - <https://www.apc.com/us/en/faqs/FA279197/>

Initial Released Version: UPS 01.0(SMC)

Compatibility:

=====

AP9613 Dry Contact Version Next Gen Relay IO card 2.1

AP9620 LCC Version 3.0

AP9624 (Second Gen Interface Expander Card) v1.0X

AP9631/AP9630 card APP SUMX 6.2.1, AOS 6.2.1

AP9635 CH / AP9631card APP SUMX 6.4.6, AOS 6.4.6

AP9635 CH card APP SUMX 6.4.0, AOS 6.4.0

PowerChute Business Edition v9.2

FUW (Firmware Upgrade Wizard) Tool v4.2.1