

Version: UPS 16.5(SMT)

Applicable SKUs:

=====

ID 1059, All standard SKUs beginning with SMT prefixes.

SMT: SMT2200R2X167

This revision revives the communication of the USB port while the UPS is on "suspend" mode when the PCBE starts recommunicating.

Change logs:

1. Increase the detection of the USB D- signal to escape the "suspended"

Note: Smart-UPS Firmware Upgrade Wizard tool

always includes the latest released firmware and helps upgrade the UPS code.

Link to tool - <https://www.apc.com/us/en/faqs/FA279197/>

Initial Released Version: UPS 16.1

Compatibility:

=====

AP9613 Dry Contact Version Next Gen Relay IO card 2.1

AP9620 LCC Version 3.0

AP9624 (Second Gen Interface Expander Card) v1.0X

AP9631/AP9630 card APP SUMX 6.2.1, AOS 6.2.1

AP9635 CH / AP9631card APP SUMX 6.4.6, AOS 6.4.6

AP9635 CH card APP SUMX 6.4.0, AOS 6.4.0

PowerChute Business Edition v9.2

FUW (Firmware Upgrade Wizard) Tool v4.2.1