

Version:

=====

UPS 14.1

Applicable SKUs:

=====

SRCE6KUXI

Compatibility:

=====

NMC SUMX v6.5 and above required to upgrade the UPS:

Web Link for instructions to upgrade the UPS Firmware using NMC - <https://www.se.com/ca/en/faqs/FA170679/>

Note: if NMC SUMX Version is below 6.5 version, Below Web link helps in upgrading the APC NMC Card with latest NMC SUMX version.

Web Link for instructions to upgrade the firmware on an APC NMC Card - <https://www.apc.com/us/en/faqs/index?page=content&id=FA156047>

Note: The Firmware Upgrade Wizard is the most reliable and preferred method of upgrading.

Release Notes (UPS 14.1):

=====

1. This release includes remediations for the security vulnerabilities listed as CVE-2022-0715 which, if compromised, may allow for potential unauthorized access and control of the device.

Change logs:

1. Function implemented to disable UPS firmware upgrades via NMC to mitigate potential risk of malicious UPS firmware being passed through this channel.
2. Enhanced UPS firmware code protection to mitigate the vulnerabilities of unauthorized extraction of confidential firmware.

Release Notes (UPS 02.4):

=====

1. Fixed low runtime warning alarm during mains mode under certain conditions.
2. Improved SOH calculation.
3. Improved charger operation performance for low/bad battery voltage.
4. Improved battery life by modifying battery detection logic.
5. Addressed unintended transfer from online to onbattery during a glitch in AC input voltage.
6. Modified product registering information in the LCD.

Release Notes (UPS 02.1):

=====

1. Addressed onbattery locking even if AC input is available and okay for Online under certain conditions.