



NOTES:
 1. USE 14 GAUGE WIRE MINIMUM, UNLESS OTHERWISE NOTED.
 ⚠ FOR SINGLE PHASE OR GROUND B PHASE SYSTEMS, B PHASE LINE TAP BE MADE ON THE C PHASE.

CONTROL POWER XFMR WIRING
 WITH 2P DISCONNECT



DWG# WD10032
 NO.