

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20170314-E103955  
**Report Reference** E103955-20160824  
**Issue Date** 2017-MARCH-14

**Issued to:** SCHNEIDER ELECTRIC INDUSTRIES SAS  
ELECTROPOLE/EYBENS, POWER / LV  
31 RUE PIERRE MENDES FRANCE  
38050 GRENOBLE CEDEX 9 FRANCE

**This is to certify that  
representative samples of**

CIRCUIT-BREAKER ACCESSORIES  
See Addendum page

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:**  
**Additional Information:**

UL 489, The Standard molded case circuit breakers  
See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20170314-E103955  
**Report Reference** E103955-20160824  
**Issue Date** 2017-MARCH-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Powerpact B 15-125A and TeSys BV4 and GV4P 2-115A accessories ;  
Auxiliary/Alarm switch Cat.Nos. LV426950 or GV4AE11, LV426951, LV426952;  
Undervoltage Release (MN) Cat.Nos. LV426801 or U027, LV426802 or GV4AU057, LV426803 or  
GV4AU137, LV426804 or GV4AU247, LV426805 or GV4AU286, LV426806 or GV4AU415, LV426807  
or GV4AU486, LV426815, LV426821, LV426822, LV426823, LV426824, LV426825, LV426826,  
LV426827, and LV426835,  
Shunt trip (MX) Cat.Nos. LV426841 or LV426850, LV426842 or LV426870, LV426843 or GV4AS027,  
LV426844 or GV4AS057, LV426846 or GV4AS137, LV426861 or GV4AS287, LV426862 or  
GV4AS487, LV426863, LV42864, and LV426866;  
Rotary handle Cat.No LV426930 or G V4ADN01, LV426931 or GV4ADN02, LV426932 or GV4APN01,  
LV426933 or GV4APN02, LV426934 or GV4APN04, LV426935 and LV426936;  
Locking devices Cat.No. 29370, LV426905, LV426906, LV426907 and LV426908.  
Interlocking device cat.No. LV426909



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

