

To read carefully before using EcoStruxure Control Expert V15.0 with M580 Safety CPUS.

CAUTION

INCORRECT BEHAVIOR

With the Safe part of M580 Safety CPUs logic programmed with Control Expert V15.0, you must install the hotfix ControlExpert_V150_HF0380584E_B to program any M580 Safety CPUs.

Failure to follow these instructions can result in injury or equipment damage.

With M580 Safety CPUs BME*58***S programmed with EcoStruxure Control Expert V15.0, when EN input of the safety EF is disabled (EN=0), its output link keeps its previous value even if it should be disabled as per the project settings.

Only the Safety M580 CPUs programmed with EcoStruxure Control Expert V15.0 are affected.

You will find complementary information on this issue and of the hotfix publication date in the technical FAQ000192199:

<https://www.se.com/us/en/faqs/FAQ000192199/>



* J Y T 3 4 0 3 3 0 1 *

Schneider
 **Electric**

July 2021