

ProSoft Configurator for Modicon - Release Notes

Version #	Date of Publication	Internal reference	Description
1.001	10/04/2019		Initial release.
1.002	14/08/2019		Added Enhanced IO Scan Option in EcoStruxure Control Expert Export. Removed project file association.
1.003	08/01/2020		Added security enhancement for DLL loading. Reinstated project file association. Added Set All Watchdog time facility Corrected issue with PCB-PTQ import
1.004	17/11/2020		<p>The GSD file decoder is able to accommodate erroneous duplicate spaces in ExtUserParameters. The Set WatchDog (All) function now also sets the main configuration. Changed Default Watchdog UI rules. Corrected issue with Slot config where allowable Module Range starts with a zero. Corrected issue with incorrect WatchDog PTQ import (tbits vs ms). GSD file Delete now supports files marked as Read-Only. Corrected Module Ext User Parameters decode of Signed16 and Signed32 allowable ranges. Added additional DP Packet Capture decoding Added DP Packet Capture Filter options. Added facility to re-order Slot Modules (Move Up / Down). Added configurable Project Properties Added Raw Slot Configuration option. (Match Legacy PTQ etc.) Block PTQ Import if Configuration Window open. Recalculate Profibus timing after PTQ import. Auto Recommend always updates Default WatchDog, (previously only updated if the Watchdog value was greater). Corrected issue where (DPV1) FailSafe is not always updated. Added GSD Joker Block support. After PCM connects, FDR Status remains "Unknown" until FDR Upload action is performed.</p>

			Corrected issue where Device Status form does not always update following a controller SWAP.
--	--	--	--