

Jun 21st, 2021

to whom It may concern

Subject: SFT2841 V17.2 – Software Release Notes.

Dear Customer,

In this document, you will find all the modifications that have been done to the Sepam settings software SFT2841, between versions 16.7 to 17.2.

Bug fix:

- a) Update Modbus Driver Suite to v14.15 due to vulnerability **CVE-2020-7523** provided by I&T (V14.14.0 or earlier).
- b) Fixed the default value for rated active power when the value is big.
- c) Printing decimal place on the exported PDF report of Settings.
- d) Add 'Courier' font on SFT2841 installation process.

Improvements:

- e) Added new settings parameters in the 49RMS protection function for motors on Sepam 80 series.

Sincerely,



Sergio FLORIDA
Product Manager Sepam relay
Schneider Electric Industries SAS

Schneider Electric Industries SAS

Postal address / Adresse postale :
Site TECHNOPOLE
28 rue Henri Tarze, Bâtiment 11
F-38050 Grenoble Cedex 9
Tel. +33 (0)4 76 57 60 60

<http://www.schneider-electric.com>

Legal information / Mentions légales
Société par actions simplifiée au capital de 928.298.512 euros
954 503 439 rcs Nanterre – code APE : 2712Z
Siret : 954 503 439 01719
n° ident. TVA : FR 04 954 503 439
Siège social : 35, rue Joseph Monier
F – 92500 Rueil-Malmaison