

Easy Cooling Row Chilled Water

Software Information List – Touch Screen

Firmware code	47106002000016		
Firmware version	62BV42X-X		
Firmware description	Design based on 62BV4-D version of standard chilled water precision air conditioner		
Corresponding controller	47402202000054		
Corresponding controller version	DQ.ERC311AD0CGE-XCRC300.SCQZJ-01		
MCU model	ARM RISC528MHz		
Current version	62BV421-I		
Software bytes or checksum	Number of bytes: 13575854 bytes		
Versions and modifications/ updates	Release	Firmware version	Main updates
	V1	62BV421-F	New archive
	V2	62BV421-I	<ol style="list-style-type: none"> Added feature to turn off alarm sound by clicking the alarm button Modified the OK key function Changed parameters position on the page

Software Information List – Motherboard

Firmware code	47103003000003		
Firmware version	332V82X-X		
Firmware description	Design based on 332V8-A version of standard chilled water precision air conditioner		
Corresponding controller	47402201000121		
Corresponding controller version	DQ.ERC311AD0CGE-XCRC300.KZQZJ-01		
MCU model	STM32F071VB		
Current version	332V82A-A1		
Software bytes or checksum	Checksum CRC = 0x84016B60		
Versions and modifications/ updates	Release	Firmware version	Main updates
	V1	332V824-A2	New archive
	V2	332V827-A1	Firmware upgrade

	V3	332V82A-A1	<ol style="list-style-type: none">1. Changed the performance of the humidity and heat during 3-phase power supply failure.2. Modified the low temperature limitation function for dehumidification.3. Modified the humidity control function.4. Modified the power supply failure function.5. Modified the function for the fan alarm "Check feedback/air flow.6. Changed the drainage failure function.7. Changed the default minimum runtime of the pump.
--	----	------------	---