

GZ1N...N,GZ1LE...N

**⚠️ ⚠️ DANGER / 危险**

**HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH.**  
Disconnect all power before servicing equipment. Failure to follow these instructions will result in death or serious injury.


**电击、爆炸或电弧闪光的危险。**  
在此电力设备上进行工作时，请先切断所有电源。  
不遵循上述说明将导致人员伤亡。

**PLEASE NOTE**


- Electrical equipment should be installed, operated, serviced, and maintained only by qualified personnel.
- No responsibility is assumed by Schneider Electric for any consequences arising out of the use of this material.

**请注意**

- 电气设备的安装、操作、维修和维护工作仅限于合格人员执行。
- Schneider Electric不承担由于使用本资料所引起的任何后果。



φ 7 mm  
1.7 N.m  
15 lb.in



≤ 6 mm

