

Changelog

Table of Contents

1	Products affected.....	2
2	New firmware features	2
3	New hardware features	2
4	Issues fixed	2
5	Known issues	3
6	Upgrade procedure.....	4

1 Products affected

Commercial reference	Product	FW version
LSS100100	Wiser for KNX	2.1.0
LSS100200	spaceLYnk	2.1.0

Table 1: Products affected

2 New firmware features

- Add optional status variable to grp.checkwrite and similar functions
- Add support for date/time/text types
- Wildcard filter for object name in Objects tab
 - Example: Object with name *01.0.G.036-MVV01_S* can be filtered by **.G.*_S*

3 New hardware features

- No changes

4 Issues fixed

- Number of items display bug in Objects tab
- Trend backup interval optimization (interval depends on total trend size)

Trend size [MB]	Backup interval [hours]
< 2	1
2	2
3	3
4 - 5	4
6 - 7	6
8 - 15	12
> 15	24

- Fix XSS in Visualization
- Fix grp.create error when no address is specified
 - Increased auto-generated range from 4K to 8K groups
- Fix 14-byte HEX data type display
- Status object – object (1bit) in visualization is updated only once

5 Known issues

- Sync project data from UI does not synchronize trends

6 Upgrade procedure

1. Click *Configurator -> System -> System -> Upgrade firmware*
2. Find firmware for your product
3. Click **OK**

Note: It is highly recommended to create backup of your actual project before upgrade!

Note: Check HW version of your logic controller. There are available HW 1.xx and HW 2.xx in parallel on the market. HW version is located in the side label of the controller.