



# Certificate of Compliance

Certificate Number: LR 115148-1

Revision:

Date Issued: March 8, 1999

Issued to: **American Power Conversion Corporation**  
174 Chesterfield Industrial Blvd.  
Chesterfield, MO 63005  
Attention: Mr. Dan Rohr

*The products listed below are eligible to bear the CSA Mark shown*



Issued by: E. Saldanha, P. Eng.  
Etobicoke, ON Canada

Signature: \_\_\_\_\_

## PRODUCTS

CLASS 3862 07 - INFORMATION TECHNOLOGY EQUIPMENT - Including Electrical Business Equipment

UPS Interface, Model AP 9220, rated 120V, 60Hz, 15A, Input/Output.

## Conditions of Acceptability

- (a) The chassis mounting holes for the Duplex Receptacles shall be masked, when coating/painting.
- (b) A properly sized starwasher shall be installed between the receptacle mounting screw head and chassis masked hole flange. The screw will be properly torqued.
- (c) The production factory test will include a ground continuity/ground impedance test conducted between the cord ground, and chassis, and each duplex receptacle, before shipment.
- (d) Replacement of a defective receptacle in the field, will be done by a qualified factory service person.

## APPLICABLE REQUIREMENTS

CAN/CSA-C22.2 No. 950-95 - Safety of Information Technology Equipment, Including Electrical Business Equipment, Third Edition.



## Supplement to Certificate of Compliance

Certificate Number: LR 115148-1

Issued to: **American Power Conversion Corporation**  
174 Chesterfield Industrial Blvd.  
Chesterfield, MO 63005  
Attention: Mr. Dan Rohr

*The products listed, including the latest revision described below,  
are eligible to be marked in accordance with the referenced Certificate.*

Issued By: E. Saldanha, P. Eng.  
Toronto, ON Canada

Signature: \_\_\_\_\_

### Product Certification History

Revision	Date	Description
-1	99/03/08	Original Certification.