

CERTIFICATE OF COMPLIANCE

Certificate Number 20161123-E177299
Report Reference E177299-A17-UL
Issue Date 2016-NOVEMBER-23

Issued to: Schneider Electric IT Corporation, FKA APC American
Power Conversion
132 Fairgrounds Rd
PO BOX 278
West Kingston RI 02892

**This is to certify that
representative samples of**

INFORMATION TECHNOLOGY EQUIPMENT INCLUDING
ELECTRICAL BUSINESS EQUIPMENT
SEE NEXT PAGE

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60950-1, 2nd Edition, 2011-12-19 (Information
Technology Equipment - Safety - Part 1: General
Requirements), CAN/CSA C22.2 No. 60950-1-07, 2nd
Edition, 2011-12 (Information Technology Equipment -
Safety - Part 1: General Requirements)

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20161123-E177299
Report Reference E177299-A17-UL
Issue Date 2016-NOVEMBER-23

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Rack Power Distribution Units

AP6007A
AP8441(*)
AP8459(#)(*)
AP8461(*)
AP8481(+)(*)

AP8541(*)
AP8558(#)(*)
AP8559(#)(*)
AP8561(*)
AP8565(*)
AP8581(+)(*)
AP8588(*)

AP8632(*)
AP8641(*)
AP8659(#)(*)
AP8661(*)
AP8681(+)(*)

AP8801X347
AP8830(*)
AP8831(*)
AP8832(*)
AP8841(*)
AP8858(#)(*)
AP8861(*)
AP8862(*)
AP8863(*)
AP8865(*)
AP8870(*)
AP8881(+)(*)

AP8930(*)
AP8931(*)
AP8932(*)
AP8941(*)
AP8941IG(*)



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20161123-E177299
Report Reference E177299-A17-UL
Issue Date 2016-NOVEMBER-23

AP8958(#)(*)
AP8959(#)(*)
AP8959IG(#)(*)
AP8961(*)
AP8961IG(*)
AP8962(*)
AP8965(*)
AP8970(*)
AP8981(+)(*)
AP8981IG(+)(*)

AP9571AX459

(#) - may be followed by WW, EA3 or NA3

(+) - may be followed by L22

(*) - may be followed by letters and/or numbers



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

