

**“Modicon MC80 Controller BMKC80x03xx” FIRMWARE HISTORY**  
 See MC80 User Manual, chapter MC80 Firmware Upgrade

**NOTICE**

Firmware downward compatibility limitation for PV 04 and above  
 => Forbid to downgrade the firmware of BMKC80x03xx (PV>=04) to SV< 1.50  
**Failure to follow these instructions can result in equipment damage.**

Version #	Date of Publication	Internal reference	Description
SV1.5	01/2020	PEP0546794R	Fixed the cyber security vulnerability of Wind River VxWorks TCP/IP Stack (IP NET)
		PEP0469386R	Enhanced to support a new NAND flash component used in MC80
		PEP0524825R	Fixed that MC80 variables parameter loss after power cycle