



### Main

Range compatibility	PacDrive 3
Product or component type	Replacement equipment
Accessory / separate part category	Spare parts
Device short name	LXMSTS
Product compatibility	SCARA robot STS80

### Complementary

Kit composition	<ul style="list-style-type: none"> <li>1.0 gearbox axis 1 STS60/80</li> <li>1.0 shaft seal ring</li> <li>1.0 o-ring axis 1 STS (bulky)</li> <li>1.0 o-ring axis 1 STS (fine)</li> <li>1.0 o-ring axis 1 STS</li> <li>16.0 washer</li> <li>16.0 screw M6 x 65</li> <li>1.0 o-ring motor axis 1 STS</li> <li>18.0 screw M8 x 60</li> <li>1.0 gearbox set axis 2 STS60/80</li> <li>1.0 gearbox axis 4 STS60/80</li> <li>1.0 toothed belt axis 4 - short</li> <li>1.0 toothed belt axis 3 STS80</li> <li>1.0 toothed belt axis 4 STS80</li> <li>2.0 deflection pulley</li> <li>6.0 bearing sleeve</li> <li>4.0 belt tightener</li> <li>6.0 washer</li> <li>6.0 screw M5 x 40</li> <li>1.0 oil castrol optigear synthetic RO 150 1L (axis 1)</li> <li>1.0 oil robolub 68-S 1L (axis 2)</li> <li>1.0 grease for ball screw</li> <li>1.0 spray for toothed belts</li> </ul>
-----------------	--

Product Life Status : **Commercialised**

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric Industries SAS nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein.