

Cybersecurity Enhancement Notice for ModbusDriverSuite

This hotfix meets the requirement of updating the ModbusDriverSuite.exe to its latest version for Cybersecurity Enhancement.

Please refer to "CVE CVE-2020-7523" for further information.

Installation step:

Please download Schneider ModbusDriverSuite.exe v14.15.0.0 from below link.

https://www.se.com/ww/en/download/document/MSCD_V14.15.0.0/

Install Schneider ModbusDriverSuite.exe v14.15.0.0 by double clicking the executable file, and wait until the installation gets completed.