

ProSoft Configurator for Modicon - Release Notes

Version #	Date of Publication	Internal reference	Description
1.001	10/04/2019		Initial release.
1.002	14/08/2019		Added Enhanced IO Scan Option in EcoStruxure Control Expert Export. Removed project file association.
1.003	08/01/2020		Added security enhancement for DLL loading. Reinstated project file association. Added Set All Watchdog time facility Corrected issue with PCB-PTQ import