



Unión Rápida 70+105
Fast Coupler 70+105


Schneider
Electric
Make the most of your energy

4530100/4532100



4530100 x 2
4532100 x 2

H=70



4530100 x 4
4532100 x 4

H=105

4599903
Rev-0

Instrucciones Técnicas de Montaje
Technical assembly instructions



Schneider Electric España, S.A.
C/Bac de Roda, 52, Edificio A - 08019 BARCELONA
Tel.:93 484 31 00 Fax.: 93 484 33 07
www.schneiderelectric.es